

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22012240/NVY3M4**Date:** 21/12/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000208		
Claimant Vehicle No :	SH9120K	Insured Vehicle No :	SLP4936Y		
Date of Loss:	06/12/2022	Nature of Claim:	TP	Claim No:	M2206974

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9120K	Engine No:	G4LEJU083483
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVHU022742
Reg. Date:	17/03/2017 (Man. Year: 2017)	Odometer:	900202 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 7 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,961.52	1,448.08	513.44	26.18
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	780.00	630.00	150.00	19.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,752.52	2,089.08	663.44	24.10
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	2,752.52	1,650.00	1,102.52	40.05
+ GST 7.00/7.00% (S\$)	192.68	115.50	77.18	40.06
Nett Amount (S\$)	2,945.20	1,765.50	1,179.70	40.06

INSPECTION

Date of Assignment:	07/12/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	07/12/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2022)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH9120K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Buckled	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Buckled	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Bent	138.10 FL	*138.10 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Bent	138.10 FL	*138.10 FL
7	1		*ANTENNA SMARTKEY	Cracked	40.50 FL	*40.50 FL
8	1		*REAR BUMPER FOG LAMP	Cracked	201.50 FL	*201.50 FL
9	1		*RENEW ADVERTISEMENT STICKER	Necessary	200.00 F	*200.00 F
10	1		*REAR NUMBER PLATE WITH TRIM COVER	Cracked	55.00 F	*55.00 F
11	1		*REAR BUMPER REVERSE SENSOR	Serviceable	180.00 F	*- F
12	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	*50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,330.65	1,733.85
- List Item Discount on L Items 20.00/20.00% (\$\$)	369.13	285.77
Total Parts (\$\$)	1,961.52	1,448.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			780.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >