

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB22012246/TQY3M4**Date:** 14/07/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447_01
Claimant Vehicle No :	SMH2145G	Insured Vehicle No :	SLV2021T
Date of Loss:	02/12/2022	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2145G	Engine No:	G4KLJH017983
Make & Model:	KIA STINGER, 2.0 2WD SUNROOF (A)	Chassis No:	KNAE351AMK6054257
Reg. Date:	16/01/2019 (Man. Year: 2018)	Odometer:	78148 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35R19	Rear Tyre Size:	255/35R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,683.81	4,189.61	12,494.20	74.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	1,450.00	2,500.00	63.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,633.81	5,639.61	14,994.20	72.67
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	20,633.81	4,500.00	16,133.81	78.19

INSPECTION

Date of Assignment:	06/12/2022		
Date Inspected:	14/12/2022	Inspected At:	Flying High Spray Painting (HQ) BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jul 2023)
Parts:	M1-SUV	KIA STINGER 2.0 2WD SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH2145G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,269.00 FL	*- FL
2	1		*BOOTLID OUTER GARNISH	Repair	385.00 FL	*- FL
3	1		*BOOTLID LOGO	Necessary	62.00 FL	*62.00 FL
4	1		*BOOTLID STINGER EMBLEM	Necessary	98.00 FL	*98.00 FL
5	2		*BOOTLID LAMP	Not Necessary	1,180.00 FL	*- FL
6	1		*BOOTLID BUZZER	Not Necessary	269.00 FL	*- FL
7	1		*BOOTLID INNER HANDLE	Not Necessary	84.00 FL	*- FL
8	1		*BOOTLID INNER LOCK	Not Necessary	124.00 FL	*- FL
9	1		*BOOTLID LOCK SENSOR	Not Necessary	320.00 FL	*- FL
10	1		*BOOTLID WEATHER STRIP	Not Necessary	147.00 FL	*- FL
11	1		*BOOTLID STRIKER	Not Necessary	85.00 FL	*- FL
12	1		*BOOTLID INNER TRIMBOARD	Not Necessary	250.00 FL	*- FL
13	1		*TAILLAMP	Not Necessary	908.00 FL	*- FL
14	1		*REAR BUMPER	Deformed	1,800.00 FL	*930.70 FL
15	1		*REAR BUMPER RETAINER	N/S Deformed/O/S Not Necessary	152.00 FL	*76.00 FL
16	1		*REAR BUMPER BRACKET	N/S Deformed/O/S Not Necessary	136.00 FL	*68.00 FL
17	2		*REAR BUMPER SIDE COVER	Not Necessary	574.00 FL	*- FL
18	1		*REAR BUMPER SIDE REFLECTOR	N/S Cracked/ O/S Not Necessary	174.00 FL	*87.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Cracked	294.00 FL	*294.00 FL
20	1		*REAR BUMPER REINFORCEMENT STAY	Bent	50.00 FL	*50.00 FL
21	2		*REAR BUMPER COVER RETAINER	Not Necessary	104.00 FL	*- FL
22	1		*REAR BUMPER CENTRE LOWER DIFFUSER	Cracked	650.00 FL	*487.40 FL
23	2		*REAR BUMPER LOWER SIDE COWLING	Not Necessary	396.00 FL	*- FL
24	1		*REAR BUMPER SPONGE	Not Necessary	235.10 FL	*- FL
25	1		*REAR BUMPER TOW COVER	Deformed	43.80 FL	*43.80 FL
26	1		*END PANEL OUTER	Repair	427.00 FL	*- FL
27	2		*REAR FENDER INNER TRIM	Not Necessary	952.00 FL	*- FL
28	2		*REAR LICENCE PLATE LAMP	Not Necessary	136.00 FL	*- FL
29	1		*TOOLS HOLDER SPONGE	Not Necessary	197.00 FL	*- FL
30	1		*REAR FLOOR PANEL	Not Necessary	794.00 FL	*- FL
31	1		*EXHAUST ASSY	Bent	578.00 FL	*578.00 FL
32	2		*EXHAUST ASSY MOUNTING	Deformed	90.00 FL	*90.00 FL
33	1		*EXHAUST HEAT SHIELD	Not Necessary	187.00 FL	*- FL
34	2		*BOOTLID HINGE	Not Necessary	270.00 FL	*- FL
35	2		*BOOTLID DAMPER	Not Necessary	354.00 FL	*- FL
36	1		*END PANEL TOP GARNISH	Deformed	168.00 FL	*168.00 FL
37	2		*REAR FENDER ARCH GARNISH	Not Necessary	724.00 FL	*- FL
38	2		*REAR BUMPER LOWER SIDE BRACKET	Not Necessary	194.00 FL	*- FL
39	1		*SET REAR BUMPER LOWER DIFFUSER CLIPS	Necessary	60.00 FS	*30.00 FS
40	12		*REAR BUMPER LOWER SIDE COWLING CLIPS	Not Necessary	66.00 FS	*- FS
41	6		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	33.00 FS	*- FS
42	6		*TAILGATE LAMP CLIPS	Not Necessary	33.00 FS	*- FS
43	10		*TAILGATE TRIMBOARD CLIPS	Not Necessary	55.00 FS	*- FS
44	6		*TAILLAMP CLIPS	Not Necessary	33.00 FS	*- FS
45	6		*END PANEL TOP GANISH CLIPS	Not Necessary	33.00 FS	*- FS
46	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

7/14/23, 5:40 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR LICENCE PLATE & FRAME	Not Necessary	55.00 FS	*- FS
48	1		*REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
49	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
50	1		*REAR FLOOR PANEL PADDING	Not Necessary	120.00 FS	*- FS
51	1		*REAR FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
52	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	100.00 FS	*- FS
53	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
54	10		*REAR BUMPER CLIPS	Necessary	55.00 FS	*30.00 FS
55	12		*REAR BUMPER SIDE COVER CLIPS	Not Necessary	66.00 FS	*- FS
56	1		*REAR BUMPER LOWER DIFFUSER	Deformed	800.00 FS	*650.00 FS
57	2		*EXHAUST TIPS	Bent	350.00 FS	*250.00 FS
58	2		*REAR EXHAUST CHROME	Bent	400.00 FS	*300.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	18,169.90 4,492.90
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,486.09 303.29
					Total Parts (\$\$)	16,683.81 4,189.61
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,600.00	600.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	30.00
3	TO REMOVE, REFIT TAILGATE COMPONENTS TO REPLACE TAILGATE, CHECK AND RE-ADJUST CLOSE GAP, ALIGNMENT AND WATER SEEPAGE	New	100.00	0.00
4	TO REMOVE AND REFIT, STRAIGHTEN AND READJUST EXHAUST PIPE AND REPLACE EXHAUST SILENCER	New	100.00	60.00
5	TO UPHOLSTER TO FACILITATE REPAIR	New	300.00	60.00
6	TO ALIGN REAR CHASSIS FRAME AND TO CONDUCT CHASSIS ALIGNMENT ON CAR-O-LINER	New	300.00	0.00
7	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL	New	1,400.00	700.00
8	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (S\$)			3,950.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >