



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 2778E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR PANEL RH	DENTED	2,933.00	1,854.90
1	FRONT DOOR OUTER HANDLE RH	NOT NECESSARY	356.00	-
1	FRONT DOOR HINGE UPPER RH	BENT	155.00	51.90
1	FRONT DOOR HINGE LOWER RH	BENT	155.00	51.90
1	FRONT DOOR CHECKER LOWER	BENT	189.00	75.30
1	FRONT DOOR LOCK RH	NOT NECESSARY	741.00	-
1	FRONT DOOR LOCK INNER BRACKET RH	NOT NECESSARY	309.00	-
1	FRONT DOOR REGULATOR AND MOTOR ASSY	NOT NECESSARY	990.00	-
1	FRONT DOOR WEATHERSTRIP	NOT NECESSARY	293.00	-
1	FRONT DOOR INNER TRIM RH	CRACKED	870.00	870.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	1,440.00	-
1	FRONT FENDER EMBLEM LOGO RH	SERVICEABLE	159.00	-
1	FRONT FENDER EMBLEM - S DRIVE 351	SERVICEABLE	109.00	-
1	FRONT BONNET	NOT NECESSARY	3,110.00	-
1	FRONT BUMPER	NOT NECESSARY	2,100.00	-
1	WING MIRROR RH	NOT NECESSARY	1,081.00	-
1	SILL GARNISH RH	NOT NECESSARY	1,339.00	-
	LESS 10% DISCOUNT		-1,632.90	-290.40
			14,696.10	2,613.60
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	40.00	20.00
1	SET FRONT DOOR INNER TRIM CLIP (SN)	NECESSARY	40.00	15.00
1	SET SILL GARNISH CLIP (SN)	NOT NECESSARY	30.00	-
			110.00	35.00
	<u>LABOUR</u>			
	CHECK WIRING AND LIGHTNING SYSTEM.		100.00	30.00
	TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW.		200.00	80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		900.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,500.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	20.00
			2,820.00	930.00
GRAND TOTAL			17,626.10	3,578.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,850.00

Report Ref No. CS3/ASM22003181/Dvp3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.