



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 8662R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	COVER, ENGINE UNDER (SN)	CRACKED	337.80	337.80
1	COVER ASSY, ENGINE (SN)	CRACKED	514.90	514.90
1	COVER, FR FLOOR, LH (SN)	CRACKED	670.10	670.10
1	COVER, FR FLOOR, RH (SN)	NOT NECESSARY	449.00	-
1	COVER, FLOOR UNDER (SN)	CRACKED	535.00	535.00
1	COVER, FLOOR UNDER (SN)	NOT NECESSARY	405.10	-
1	BRACE, FR SUSPENSION (SN)	NOT NECESSARY	136.00	-
1	BRACE, FR SUSPENSION (SN)	NOT NECESSARY	136.00	-
1	MEMBER SUB-ASSY, RR (SN)	NOT NECESSARY	3,123.30	-
1	CUSHION, RR SUSP (SN)	NOT NECESSARY	153.80	-
1	CUSHION, RR SUSP (SN)	NOT NECESSARY	163.40	-
1	ABSORBER ASSY (SN)	NOT NECESSARY	562.50	-
1	ABSORBER ASSY (SN)	NOT NECESSARY	567.40	-
1	ARM SUB-ASSY (SN)	NOT NECESSARY	945.30	-
1	ARM SUB-ASSY (SN)	NOT NECESSARY	945.30	-
2	JOINT ASSY, LWR BALL (SN)	NOT NECESSARY	567.20	-
1	KNUCKLE, STEERING (SN)	NOT NECESSARY	875.10	-
1	KNUCKLE, STEERING (SN)	NOT NECESSARY	875.10	-
2	HUB & BEARING ASSY (SN)	NOT NECESSARY	1,453.80	-
1	SHAFT ASSY, FR (SN)	NOT NECESSARY	1,528.10	-
1	SHAFT ASSY, FR (SN)	NOT NECESSARY	1,775.00	-
1	GEAR ASSY, ELECTRIC (SN)	NOT NECESSARY	7,728.40	-
2	ROD ASSY, TIE (SN)	NOT NECESSARY	383.00	-
1	GASKET, EXHAUST PIPE (SN)	NOT NECESSARY	29.50	-
1	PIPE ASSY, EXHAUST (SN)	BENT	3,055.60	3,055.60
1	GASKET, EXHAUST PIPE (SN)	NOT NECESSARY	63.50	-
1	PIPE ASSY, EXHAUST (SN)	BENT	1,920.90	1,920.90
1	TRANSAXLE ASSY (SN)	CRACKED	22,518.80	22,518.80
2	ABSORBER ASSY (SN)	NOT NECESSARY	302.40	-
2	ARM ASSY, RR (SN)	NOT NECESSARY	1,031.00	-

Report Ref No. CS/FCI22012256/Rqy3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CARRIER SUB-ASSY, RR (SN)	NOT NECESSARY	961.10	-
1	CARRIER SUB-ASSY, RR (SN)	NOT NECESSARY	961.10	-
1	COVER, LWR CONTROL (SN)	NOT NECESSARY	118.40	-
1	COVER, LWR CONTROL (SN)	NOT NECESSARY	128.80	-
1	ARM ASSY, TRAILING (SN)	NOT NECESSARY	466.30	-
1	ARM ASSY, TRAILING (SN)	NOT NECESSARY	466.30	-
1	PAN SUB-ASSY, OIL (SN)	BENT	336.80	336.80
1	BALANCER ASSY (SN)	NOT NECESSARY	1,080.30	-
5	TRD MOTUL ENG OIL 5W30 (SN)	NOT NECESSARY	212.50	-
1	OIL FILTER (SN)	NOT NECESSARY	40.30	-
1	CVT FE (4L) (SN)	NECESSARY	209.00	209.00
1	BAFFLE SUB-ASSY (SN) (ADDITIONAL)	NECESSARY	188.50	188.50
1	SEALANT (SN) (ADDITIONAL)	NECESSARY	143.60	143.60
1	TANK SUB-ASSY, FUEL (SN) (ADDITIONAL)	DEFORMED	1,387.20	1,387.20
1	COVER ASSY, ENGINE (SN) (ADDITIONAL)	BENT	795.50	795.50
1	BAFFLE SUB-ASSY (SN) (ADDITIONAL)	NECESSARY	188.50	188.50
2	COOLANT, SLLC&&& (SN) (ADDITIONAL)	NECESSARY	191.00	191.00
2	GASKET, FUEL SUCTION (SN) (ADDITIONAL)	NECESSARY	98.80	98.80
			61,756.30	33,122.00
	<b>LABOUR</b>			
	REPLACE FRT ENGINE LOWER COVER AND DAMAGED PARTS. REMOVE & INSTALL COMPONENTS TO ASSIST REPAIR.		1,584.00	792.00
	REMOVE & INSTALL EXHAUST PIPE ASSY TO ASSIST REPAIR.		792.00	792.00
	REMOVE & INSTALL FRT SUSPENSION SYSTEM ASSY TO ASSIST REPAIR.		1,584.00	1,584.00
	REMOVE & INSTALL REAR SUSPENSION SYSTEM ASSY TO ASSIST REPAIR.		1,584.00	1,584.00
	TO LIFT UP ENGINE, REMOVE & INSTALL COMPONENTS TO ASSIST REPAIR.		2,376.00	1,584.00
	REMOVE & INSTALL GEARBOX ASSY TO ASSIST REPAIR.		1,584.00	1,584.00
	CONDUCT FULL WHEEL ALIGNMENT.		198.00	198.00

Report Ref No. CS/FCI22012256/Rqy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESET ECU AND REPROGRAMME.		198.00	198.00
			9,900.00	8,316.00
GRAND TOTAL			71,656.30	41,438.00
RECOMMENDED COST OF REPAIRS				41,438.00

Report Ref No. CS/FCI22012256/Rqy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.