

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012257/TWP3Q2**Date:** 13/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00244382108

Claimant Vehicle No : GBG6584G **Insured Vehicle No :** SJR1381E

Date of Loss: 01/12/2022 Nature of Claim: TP Claim No: SNM22D208676/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG6584G**

Make & Model: NISSAN NV350, 2.5 (A) Engine No: YD25000639B

Reg. Date: 27/09/2017 (Man. Year: 2017) Chassis No: JN1MC2E26Z0009519

Colour: Silver Odometer: 199611 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,422.00	988.88	4,433.12	81.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	2,650.00	1,390.00	34.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,462.00	3,638.88	5,823.12	61.54
+ GST 8.00/8.00% (S\$)	756.96	291.11	465.85	61.54
Nett Amount (S\$)	10,218.96	3,929.99	6,288.97	61.54

INSPECTION

Date of Assignment: 07/12/2022

Date Inspected: 09/12/2022 Inspected At: 19 UBI ROAD 4
Repairer: Tan Chong Motor Sales Pte Ltd (Toa Payoh)

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Jun 2023)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG6584G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM -BACK DOOR NV350 & URBAN	Necessary	118.70 FN	*118.70 FN
2	1		*EMBLEM -REAR NISSAN	Necessary	70.00 FN	*70.00 FN
3	1		*GLASS -TAIL GATE	Not Necessary	961.20 FN	*- FN
4	1		*TAIL GATE	Repair	1,961.00 FN	*- FN
5	10		*CLIP RR BUMPER	Necessary	14.00 FN	*14.00 FN
6	1		*REAR BUMPER	Deformed	720.60 FN	*720.60 FN
7	1		*LH RR FENDER	Repair	2,169.20 FN	*- FN
8	1		*TAILLAMP RH	Cracked	250.30 FN	*250.30 FN
9	1		*LABEL (8 PCS)	Necessary	15.00 FS	*15.00 FS
10	1		*70KM/H	Necessary	15.00 FS	*15.00 FS
11	1		*SENSOR -REVERSE	Not Necessary	250.00 FS	*- FS
12	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
13	1		*REAR W/SCREEN SEALANT	Not Necessary	80.00 FS	*- FS
					Sub Total (S\$)	6,675.00 1,223.60
					- Nett Item Discount on N Items 20.00/20.00% (S\$)	1,253.00 234.72
					Total Parts (S\$)	5,422.00 988.88

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR CHARGES TO RENEW LH RR FENDER ,TAIL GATE AND REAR BUMPER REPAIR OUTER END PANEL REAR	New	1,950.00	1,400.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,250.00	750.00
3	REMOVE/INSTALL RENEW REVERSE SENSOR	New	110.00	110.00
4	RENEW REAR WINDSCREEN GLASS	New	240.00	0.00
5	REMOVE AND INSTALL LH RR FENDER WINDOW PANEL	New	190.00	190.00
6	APPLY SEALANT TO TAILGATE	New	100.00	0.00
7	RENEW LH RR COMB LAMP AND CHECK LIGHTING SYSTEM	New	80.00	80.00
8	PERFORM RUSTPROOFING LH RR FENDER PANEL	New	120.00	120.00
Gross Labour Cost (\$\$)			4,040.00	2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >