

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22012266/RQP3E2**Date:** 31/05/2023**REFERENCE**

Insured/Claimant:	PEH CHYE HENG	Policy No:	1800110079-02	
Date of Loss:	04/12/2022	Nature of Claim:	OD	Claim No: 7666312293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6616S	Engine No:	CYG024756
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4G2JN060338
Reg. Date:	30/08/2018 (Man. Year: 2017)	Odometer:	62637 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	63,663.00	30,897.52	32,765.48	51.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,144.00	8,769.00	6,375.00	42.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	78,807.00	39,666.52	39,140.48	49.67
- Excess (\$\$)	900.00	900.00	0.00	0.00
(\$\$)	77,907.00	38,766.52	39,140.48	50.24
+ GST 8.00/8.00% (\$\$)	6,232.56	3,101.32	3,131.24	50.24
Nett Amount (\$\$)	84,139.56	41,867.84	42,271.72	50.24

INSPECTION

Date of Assignment:	08/12/2022		
Date Inspected:	07/12/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days		

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	3,475.00 FS	*2,780.00 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	567.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	143.00 FS	*- FS
4	2	*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	84.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT	Cracked	237.00 FS	*189.20 FS
6	1	*FRONT BUMPER LOWER SPOILER	Repair	276.00 FS	*- FS
7	1	*FRONT BUMPER LOWER TRIM SPOILER	Not Necessary	1,054.00 FS	*- FS
8	1	*RADIATOR GRILLE	Cracked	2,140.00 FS	*1,712.00 FS
9	1	*RADIATOR GRILLE COVER	Missing	41.00 FS	*32.24 FS
10	2	*RADIATOR GRILLE SENSOR SUPPORT - LH / RH	Necessary	148.00 FS	*117.92 FS
11	2	*FRONT PARKING AID SENSOR - INNER	Not Necessary	531.00 FS	*- FS
12	2	*FRONT PARKING AID SENSOR - OUTER	Not Necessary	531.00 FS	*- FS
13	4	*FRONT PARKING AID SEAL RING	Not Necessary	6.00 FS	*- FS
14	1	*SET FRONT BUMPER WIRING	Not Necessary	642.00 FS	*- FS
15	1	*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	O/S Missing / N/S NotNecessary	1,286.00 FS	*514.00 FS
16	1	*FRONT CHANNEL COVER - LH / RH	O/S Cracked / N/S NotNecessary	116.00 FS	*45.68 FS
17	1	*FRONT WHEEL SPOILER - LH / RH	O/S Cracked / N/S NotNecessary	588.00 FS	*234.80 FS
18	1	*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	927.00 FS	*- FS
19	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	265.00 FS	*- FS
20	2	*FRONT BUMPER BRACKET HOLDER - LH / RH	Not Necessary	582.00 FS	*- FS
21	2	*FRONT BUMPER BRACE - LH / RH	Not Necessary	68.00 FS	*- FS
22	2	*FRONT BUMPER GUIDE PIECE - LH / RH	Not Necessary	84.00 FS	*- FS
23	1	*FRONT BUMPER TOP COVER	Cracked	137.00 FS	*109.60 FS
24	1	*AIR CONDITIONER STICKER	Necessary	22.00 FS	*17.44 FS
25	1	*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
26	1	*HORN LOW TONE - LH	Not Necessary	214.00 FS	*- FS
27	1	*HORN HIGH TONE - RH	Not Necessary	214.00 FS	*- FS
28	2	*HORN BRACKET - LH / RH	Not Necessary	106.00 FS	*- FS
29	2	*FRONT FENDER - LH / RH	Repair	3,120.00 FS	*- FS
30	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	107.00 FS	*- FS
31	2	*FRONT FENDER BRACE - LH / RH	Not Necessary	214.00 FS	*- FS
32	2	*FRONT DOOR STONE GUARD FILM - LH / RH	Necessary	270.00 FS	*216.00 FS
33	2	*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	620.00 FS	*- FS
34	1	*BONNET	Bent	5,736.00 FS	*4,588.80 FS
35	2	*BONNET HINGE - LH / RH	Bent	358.00 FS	*286.40 FS
36	1	*BONNET CATCH HOOK	Bent	155.00 FS	*124.00 FS
37	1	*BONNET LOCK - LH / RH	O/S Bent / N/S NotNecessary	455.00 FS	*182.00 FS
38	2	*BONNET LOCK BAR - LH / RH	Bent	111.00 FS	*88.80 FS
39	1	*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
40	1	*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
41	1	*BONNET LOCK COVER	Not Necessary	4.00 FS	*- FS
42	1	*BONNET CATCH HOOK	Not Necessary	20.00 FS	*- FS
43	1	*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
44	2	*HEADLIGHT MOUNTING - LH / RH	Cracked	264.00 FS	*210.40 FS
45	2	*HEADLIGHT - LH / RH	Cracked	20,294.00 FS	*16,235.20 FS
46	1	*HEADLIGHT POWER MODULE	Not Necessary	635.00 FS	*- FS
47	1	*HEADLIGHT POWER MODULE	Not Necessary	625.00 FS	*- FS
48	1	*HEADLIGHT RANGE CONTROL MOTOR	Not Necessary	362.00 FS	*- FS
49	1	*HEADLIGHT FAN - RH	Not Necessary	428.00 FS	*- FS
50	1	*HEADLIGHT HOSE	Not Necessary	40.00 FS	*- FS
51	1	*HEADLIGHT ADJUSTMENT ELEMENT - LH / RH	O/S Necessary/N/S NotNecessary	102.00 FS	*40.56 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*HEADLIGHT COMPENSATING PIECE (4PCS)	Necessary (2Pcs Only)	185.00 FS	*73.92 FS
53	2	*LIFT CYLINDER - LH / RH	Not Necessary	518.00 FS	*- FS
54	2	*LIFT CYLINDER COVER CAP - LH / RH	Not Necessary	128.00 FS	*- FS
55	1	*LIFT CYLINDER HOSE	Not Necessary	553.00 FS	*- FS
56	1	*LOCK CARRIER	Cracked	1,385.00 FS	*1,108.00 FS
57	2	*LOCK CARRIER SUPPORT - LH / RH	Not Necessary	83.00 FS	*- FS
58	1	*CHARGE AIR COOLER	Not Necessary	628.00 FS	*- FS
59	1	*PULSATON DAMPER	Not Necessary	88.00 FS	*- FS
60	1	*CHARGE AIR COOLER PRESSURE PIPE - LH	Not Necessary	262.00 FS	*- FS
61	1	*CHARGE AIR COOLER PRESSURE HOSE	Not Necessary	76.00 FS	*- FS
62	1	*A/C CONDENSER	Bent	829.00 FS	*662.80 FS
63	1	*A/C CONDENSER REFRIGERANT HOSE	Not Necessary	286.00 FS	*- FS
64	1	*A/C CONDENSER REFRIGERANT PIPE	Not Necessary	286.00 FS	*- FS
65	1	*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	26.00 FS	*- FS
66	1	*RADIATOR	Bent	897.00 FS	*717.20 FS
67	6	*READY-MIX COOLANT	Necessary	297.00 FS	*237.12 FS
68	2	*RADIATOR AIR GUIDE - LH / RH	Cracked	172.00 FS	*137.12 FS
69	1	*RADIATOR AIR GUIDE SEALING STRIP	Not Necessary	54.00 FS	*- FS
70	1	*RADIATOR AIR GUIDE COVER - UPPER CENTRE	Not Necessary	32.00 FS	*- FS
71	1	*INTAKE AIR DUCT - RH	Not Necessary	101.00 FS	*- FS
72	1	*RADIATOR AIR GUIDE - RH	Not Necessary	31.00 FS	*- FS
73	1	*FRONT DISTANCE SENSOR - RH	Not Necessary	7,495.00 FS	*- FS
74	1	*FRONT DISTANCE SENSOR FRAME COVER - RH	Not Necessary	15.00 FS	*- FS
75	1	*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
76	1	*SUNDRIES	Necessary	500.00 FS	*85.28 FS
77	1	*FRONT REINFORCEMENT BEAM SUPPORT - LH (Supplementary)	Cracked	15.00 FS	*11.52 FS
78	1	*WATER DEFLECTOR - LH (Supplementary)	Cracked	84.00 FS	*67.12 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 63,663.00 30,897.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,600.00	1,600.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	2,750.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDER, BONNET AND HINGES	New	5,000.00	2,575.00
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION	New	480.00	480.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			15,144.00	8,769.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >