



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 5968P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	STEP PLATE (SN)	DEFORMED	631.24	631.24
1	FRONT FOG LAMP (SN)	SCRATCHED	402.58	402.58
1	BUMPER, FRONT (SN)	DEFORMED	564.79	564.79
1	BRACKET (SN)	BENT	145.09	145.09
1	FACING (SN)	SCRATCHED	56.76	56.76
1	FRONT SPOILER (SN)	DEFORMED	250.51	250.51
1	FACING (SN)	SCRATCHED	39.63	39.63
1	LAMP UNIT (SN)	SCRATCHED	831.96	831.96
1	END CAP (SN) (ADDITIONAL)	NECESSARY	32.10	32.10
1	COVER FRAME (SN) (ADDITIONAL)	SCRATCHED	172.14	172.14
			3,126.80	3,126.80
<b><u>LABOUR</u></b>				
	TO REPAIR FRONT LEFT ACCIDENT AREA.		1,800.00	1,560.00
			1,800.00	1,560.00
<b>GRAND TOTAL</b>			<b>4,926.80</b>	<b>4,686.80</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,686.80</b>

Report Ref No. CS/LIP22012269/Rvy3m4

MARKET VALUE: \$220,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$26,815.00=NETT VALUE: \$193,185.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.