



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 6266U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	TORN	1,260.75	1,260.75
4	TAPE,PROTECTOR @\$4.64	NECESSARY	18.56	18.56
1	RETAINER S.S ULTRASONIC CENTER	NOT NECESSARY	15.77	-
1	RETAINER S.S ULTRASONIC SIDE	NECESSARY	15.77	15.77
1	SENSOR ULTRASONIC CENTER	NOT NECESSARY	184.59	-
1	SENSOR ULTRASONIC SIDE	SHORTED	184.59	184.59
1	BRACEKT CENTER REAR BUMPER	NOT NECESSARY	4.64	-
1	REAR REINFORCEMENT	BENT	523.08	523.08
1	RETAINER RH REAR	BENT	41.73	41.73
1	RETAINER LH REAR	NOT NECESSARY	41.73	-
1	REFLECTOR RH	CRACKED	49.65	49.65
1	COVER TOWING HOOK RH REAR	TORN	56.22	56.22
1	SPLASH SHIELD RH REAR	NOT NECESSARY	63.05	-
6	FASTENER @\$2.36	NECESSARY	14.16	14.16
1	COVER UNDER CENTER REAR BUMPER	NOT NECESSARY	147.34	-
2	RIVET @\$7.42	NECESSARY	14.84	14.84
6	FASTENER @\$7.34	NECESSARY	44.04	44.04
2	TAPE SEAL @\$13.91	NECESSARY	27.82	27.82
4	GROMMET,SCREW @\$2.36	NECESSARY	9.44	9.44
1	GASKET RH TAIL LAMP	NECESSARY	52.77	52.77
1	GASKET LH TAIL LAMP	NECESSARY	52.77	52.77
1	SILENCER MAIN EXHAUST	SERVICEABLE	1,704.51	-
1	GASKET EXHAUST	NOT NECESSARY	27.23	-
1	BRACKET RH,BSM (ADDITIONAL)	CRACKED	101.91	101.91
			4,656.96	2,468.10
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
<b><u>LABOUR</u></b>				
TO REPLACE REAR BUMPER.			800.00	660.00

Report Ref No. CS/SMR22012273/Uqy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY REAR BUMPER.		700.00	630.00
	TO REPLACE REVERSE SENSOR.	NOT NECESSARY	660.00	-
	TO REPLACE REAR EXHAUST.	NOT NECESSARY	660.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		300.00	180.00
	REPAIR REAR END PANEL (ADDITIONAL).		330.00	330.00
	SPRAY REAR END PANEL (ADDITIONAL).		315.00	315.00
			4,015.00	2,235.00
<b>GRAND TOTAL</b>			<b>8,721.96</b>	<b>4,723.10</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,723.10</b>
------------------------------------	--	--	--	-----------------

Report Ref No. CS/SMR22012273/Uqy3m4

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.