



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 9706Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR O/S	BADLY DENTED	1,162.00	1,162.00
1	FRONT DOOR MIRROR ASSY O/S	CRACKED	485.60	485.60
1	FRONT DOOR MIRROR COVER O/S	BROKEN	98.50	98.50
1	FRONT DOOR OUTER HANDLE O/S	CUT	245.80	245.80
1	FRONT DOOR OUTER HANDLE KNOB END O/S	CUT	26.00	26.00
1	FRONT DOOR INNER LOCK O/S	DAMAGED	275.40	275.40
1	FRONT DOOR GLASS O/S	CUT	545.20	545.20
1	FRONT DOOR GLASS OUTER CHROME MOULDING O/S	BENT	182.60	182.60
1	FRONT DOOR GLASS TOP CHROME MOULDING O/S	NECESSARY	188.90	188.90
1	FRONT DOOR QUARTER GLASS GARNISH O/S	GRAZED	142.60	142.60
1	FRONT DOOR INNER TRIM BOARD O/S	NOT NECESSARY	455.20	-
1	FRONT DOOR INNER RUBBER O/S	NECESSARY	188.90	188.90
1	REAR DOOR O/S	TO REPAIR SEE LABOUR	1,385.20	-
1	REAR DOOR OUTER HANDLE O/S	CUT	245.50	245.50
1	REAR DOOR OUTER HANDLE KNOB END O/S	CUT	26.00	26.00
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	1,229.80	-
1	TAILLAMP O/S	SCRATCHED	751.00	751.00
	LESS 20% DISCOUNT		-1,526.84	-912.80
			6,107.36	3,651.20
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.		80.00	50.00
	TO TRANSFER FRONT DOOR MECHANISM O/S.		100.00	60.00
	TO DISMANTLE & REFIX REAR TRIM GARNISH.	NOT NECESSARY	180.00	-
	TO SPRAY RUST PROOFING.		100.00	40.00
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.		180.00	100.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR O/S AND REAR FENDER O/S.		800.00	600.00

Report Ref No. CS/TP22012277/Uny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,200.00	900.00
			2,690.00	1,770.00
GRAND TOTAL			8,797.36	5,421.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CS/TP22012277/Uny3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.