

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012278/GQP3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00173622203	
Claimant Vehicle No :	SLH8667P	Insured Vehicle No :	SMP168L	
Date of Loss:	06/12/2022	Nature of Claim:	TP	Claim No: SNM22D208757/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH8667P		Engine No:	2ZRR964987
Make & Model:	TOYOTA PRIUS, 1.8 (A)		Chassis No:	JTDKB3FU203537952
Reg. Date:	22/11/2016 (Man. Year: 2016)		Odometer:	278421 km
Colour:	Silver			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,581.60	5,673.89	9,907.71	63.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	2,510.00	2,120.00	45.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,211.60	8,183.89	12,027.71	59.51
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	20,211.60	6,500.00	13,711.60	67.84
+ GST 8.00/8.00% (S\$)	1,616.93	520.00	1,096.93	67.84
Nett Amount (S\$)	21,828.53	7,020.00	14,808.53	67.84

INSPECTION

Date of Assignment:	07/12/2022	
Date Inspected:	07/12/2022 Inspected At:	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH8667P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,598.00 FL	*1,147.00 FL
2	2		*TAILGATE LAMP	Not Necessary	918.00 FL	*- FL
3	1		*TAILGATE WEATHERSTRIP	Twisted	212.00 FL	*212.00 FL
4	1		*TAILGATE OUTER GARNISH	Not Necessary	521.00 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	95.50 FL	*47.90 FL
6	1		*TAILGATE EMBLEM PRIUS T	Necessary	89.40 FL	*54.60 FL
7	1		*TAILGATE EMBLEM HYBRID	Necessary	82.30 FL	*54.60 FL
8	1		*TAILGATE DETECTOR	Cracked	321.00 FL	*128.40 FL
9	1		*TAILGATE LOCK	Cut	312.00 FL	*312.00 FL
10	1		*TAILGATE WINDSCREEN MOULDING	Necessary	198.00 FL	*160.00 FL
11	1		*TAILGATE INNER TRIM BOARD	Not Necessary	459.00 FL	*- FL
12	1		*TAILGATE INNER HANDLE	Not Necessary	38.00 FL	*- FL
13	1		*TAILGATE REAR LOWER GLASS MOULDING	Necessary	157.00 FL	*157.00 FL
14	1		*REAR BUMPER	Distorted	798.00 FL	*558.39 FL
15	1		*REAR BUMPER SIDE RETAINER	N/S Cut	224.00 FL	*112.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	422.00 FL	*360.10 FL
17	2		*REAR BUMPER BRACKET	No such part	228.00 FL	*- FL
18	1		*REAR BUMPER LIP	Distorted	728.90 FL	*552.60 FL
19	2		*REAR BUMPER REFLECTOR	Not Necessary	136.00 FL	*- FL
20	1		*REAR BUMPER UNDER COVER LH	Distorted	321.00 FL	*232.00 FL
21	1		*REAR BUMPER TOP LAMP	O/S Not Necessary / N/SCracked	502.00 FL	*251.00 FL
22	1		*REAR BUMPER UNDER COVER CENTRE	Not Necessary	312.00 FL	*- FL
23	2		*REAR FENDER COWLING	Deformed (1 PCS ONLY)	396.40 FL	*198.20 FL
24	2		*REAR FENDER INNER TRIM (LOWER)	Not Necessary	1,218.00 FL	*- FL
25	2		*REAR FENDER SIDE TOP GARNISH	Not Necessary	136.00 FL	*- FL
26	1		*TAILAMP	O/SNot Necessary/ N/S Cracked	1,388.00 FL	*548.40 FL
27	2		*TAILAMP LOWER BRACKET	Not Necessary	164.00 FL	*- FL
28	2		*TAILAMP LOWER PANEL	Repair	628.00 FL	*- FL
29	1		*REAR END PANEL	Bent	612.00 FL	*612.00 FL
30	1		*REAR END PANEL TOP GARNISH	Deformed	212.00 FL	*165.00 FL
31	1		*REAR FLOOR PANEL	Repair	1,151.00 FL	*- FL
32	1		*REAR FLOOR PANEL TOP BOARD	Bent	398.00 FL	*398.00 FL
33	1		*REAR FLOOR PANEL TOP SIDE SPONGE	N/S Cut	624.00 FL	*312.00 FL
34	2		*REAR CHASSIS EXTENSION	Repair	650.00 FL	*- FL
35	1		*REAR EXHAUST PIPE	Not Necessary	1,125.00 FL	*- FL
36	1		*REAR EXHAUST PIPE HEAT SHIELD	Distorted	312.00 FL	*312.00 FL
37	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	52.00 FL	*- FL
38	1		*REAR BUMPER TOP MAT	Not Necessary	100.00 FS	*- FS
39	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
40	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*30.00 FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*50.00 FS
42	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
43	1		*REAR LOWER GLASS SEALANT	Necessary	80.00 FS	*50.00 FS
44	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
46	1		*REAR NUMBER PLATE GARNISH	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
48	1		*REAR REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
49	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*30.00 FS
50	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)					19,129.50	7,395.19
- List Item Discount on L Items 20.00/25.00% (\$)					3,547.90	1,721.30
Total Parts (\$)					15,581.60	5,673.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	150.00	30.00
2	REMOVE AND REFIR REAR LOWER GLASS	New	100.00	80.00
3	TO REMOVE AND RENEW REVERSE SENSOR	New	150.00	40.00
4	TO REMOVE AND REFIT REAR GLASS	New	150.00	120.00
5	REMOVE AND RENEW REAR GARNISH /UPHOLSTERY	New	300.00	60.00
6	REMOVE AND RENEW TAILGATE MECHANISM	New	80.00	60.00
7	REMOVE AND RENEW REAR EXHAUST SILENCER	New	150.00	60.00
8	TO RESPRAY UNDERCOATING	New	150.00	60.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	0.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,000.00
11	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	1,000.00
Gross Labour Cost (S\$)			4,630.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >