

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012283/UPA3Q2**Date:** 14/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100486583-06
Claimant Vehicle No :	GBL7302X	Insured Vehicle No :	GBF4261G
Date of Loss:	03/12/2022	Nature of Claim:	TP
		Claim No:	8049174795SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL7302X		
Make & Model:	KIA K2500 6M/T, 2.5 D (M)	Engine No:	D4CBM289117
Reg. Date:	04/03/2022 (Man. Year: 2021)	Chassis No:	KNCSJX76LM7560658
Colour:	White	Odometer:	23403 km
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	145 R13 (D)
Front Left Side:	Hankook 8 mm	Rear Left Side:	Hankook 8/8 mm
Front Right Side:	Hankook 8 mm	Rear Right Side:	Hankook 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,888.30	2,343.00	545.30	18.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,075.00	1,050.00	1,025.00	49.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,963.30	3,393.00	1,570.30	31.64
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	4,963.30	2,700.00	2,263.30	45.60
+ GST 7.00/7.00% (S\$)	347.43	189.00	158.43	45.60
Nett Amount (S\$)	5,310.73	2,889.00	2,421.73	45.60
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,211.00		

INSPECTION

Date of Assignment:	08/12/2022	
Date Inspected:	08/12/2022	Inspected At: NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254 Singapore 528839
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR CABIN TAILGATE CENTER DOOR	Dented / Bent	1,299.00 FL	*1,050.00 FL
2	1		*REAR 70 STICKER	Necessary	132.30 FS	*10.00 FS
3	1		*REAR LAMP PANEL (O/S)	Bent	221.00 FL	*221.00 FL
4	1		*REAR LAMP ASSEMBLY (O/S)	Cracked	169.00 FL	*169.00 FL
5	1		*REAR NUMBER PLATE LAMP	Cut	51.00 FL	*51.00 FL
6	1		*REAR TAILGATE DOOR LOWER BODY PANEL	Repair	221.00 FL	*- FL
7	1		*REAR CABIN LOWER STEP SUPPORT BAR	Bent	399.00 FL	*399.00 FL
8	1		*REAR CABIN TAILGATE DOOR TOP RUBBER	Bent	480.00 FL	*480.00 FL
9	1		*SET REAR PARKING SENSOR	Shorted	200.00 FS	*200.00 FS
					Sub Total (\$\$)	3,172.30 2,580.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	284.00 237.00
					Total Parts (\$\$)	2,888.30 2,343.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND INSTALL REAR DOOR ,REAR LAMP ,REAR LAMP PANEL ,REAR STEP BAR ,CUT OUT AND RENEW REAR CABIN INNER PANEL,KNOCKING REAR CABIN FLOORBOARD ,RESTRAIGHTEN BODY AND CHASSIS	New	850.00	580.00
2	SPRAY PAINTING	New	750.00	450.00
3	CHECK WIRING SYSTEM	New	25.00	20.00
4	REMOVE AND INSTALL REAR CABIN AND RE-ADJUST REAR CABIN	New	450.00	0.00
Gross Labour Cost (S\$)			2,075.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >