

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond. Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

27/12/22 4/5 @ 2000 informed Elin

15 December 2022

REG NO.: SLS 5528 U

MAKE/MODEL: BMW I3

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front door (RH) <i>R</i>	\$ 1,605.00 X
1	Front door, lower garnish <i>corn</i>	\$ 197.00
1	Rear fender <i>R</i>	\$ 1,550.00 X
1	Rear bumper <i>de/torn</i>	\$ 1,035 1,495.00
		\$ 4,847.00
	<i>102</i> Less 5%	\$ 242.35
		\$ 4,604.65

S/N	LABOUR CHARGES	
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 <i>20</i>
2	To remove and refit inner garnishes.	\$ 150.00 X
3	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$ 200.00 X
4	To apply undercoating.	\$ 180.00 X
5	Panel beating.	\$ 1,500.00 <i>580</i>
6	To re-spray painting on the affected areas.	\$ 1,400.00 <i>800</i>
		\$ 3,510.00

GRAND TOTAL :

\$ 8,114.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1232
102
11088
1400
2508.60
202
2007.