

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 6621B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WHEEL (CONSISTENT)	WARPED	495.00	450.00
2	FRONT WHEEL BEARING (CONSISTENT)	NECESSARY	65.00	65.00
1	FRONT WHEEL SHAFT (CONSISTENT)	BENT	24.00	24.00
1	FRONT BRAKE DISC (CONSISTENT)	WARPED	90.00	90.00
1	FRONT MURGUARD (CONSISTENT)	BROKEN	110.00	110.00
1	FRONT FORK ASSY FULL COMPLETE (CONSISTENT)	CRACKED	1,350.00	1,100.00
1	STEERING CONE BEARING (CONSISTENT)	NECESSARY	110.00	110.00
1	FRONT GRILLE 'R' (CONSISTENT)	CRACKED	65.00	65.00
1	HEADLAMP (CONSISTENT)	CRACKED	350.00	283.00
1	HEAD FAIRING (CONSISTENT)	CRACKED	280.00	280.00
1	LOWER CENTER FAIRING (CONSISTENT)	CUT	180.00	180.00
1	LOWER SIDE FOOTREST FAIRING 'R' (CONSISTENT)	CRACKED	140.00	140.00
1	FRONT DASH BOARD WITH KEY HOLE (CONSISTENT)	CRACKED	220.00	180.00
1	REAR LOWER TAILLAMP FAIRING (CONSISTENT)	CRACKED	65.00	65.00
1	EXHAUST PIPE (CONSISTENT)	TO REPAIR SEE LABOUR	1,200.00	-
1	EXHAUST METAL SMALL COVER (CONSISTENT)	CUT	35.00	35.00
1	EXHAUST LONG COVER (CONSISTENT)	CUT	98.00	98.00
1	EXHAUST END COVER (CONSISTENT)	CUT	58.00	58.00
1	WINDSCREEN (CONSISTENT)	CUT	668.00	623.00
1	V FAIRING THAT COVER THE HEADLAMP (CONSISTENT)	CUT	107.00	107.00
	LESS 10% DISCOUNT		-	-406.30
			5,710.00	3,656.70
	<u>LABOUR</u>			
	TOW.		50.00	50.00
	LABOUR.INCLUSIVE OF THE REPAIR OF EXHAUST PIPE		580.00	380.00
			630.00	430.00
	GRAND TOTAL		6,340.00	4,086.70

Report Ref No. CC4/ASM22012290/Upa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,200.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CC4/ASM22012290/Upa3q2

CHUA KANG SENG

Licensed Appraiser