

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122012293/KQY3Q2**Date:** 15/03/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMW3397K**Insured Vehicle No :** YP6157L

Date of Loss: 03/12/2022

Nature of Claim: TP

Claim No: CDMCG22002616

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMW3397K**Make & Model: MERCEDES-BENZ CLA180, 1.3 COUPE
PROGRESSIVE (A)

Engine No: 28291480397087

Reg. Date: 15/11/2020 (Man. Year: 2020)

Chassis No: W1K1183842N134816

Colour: Metallic Grey

Odometer: 43682 km

Engine Capacity: 1332 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Hankook 4 mm

Rear Left Side: Hankook 5 mm

Front Right Side: Hankook 4 mm

Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,677.90	7,587.00	1,090.90	12.57
Miscellaneous Items	350.00	140.00	210.00	60.00
Labour	2,730.00	2,140.00	590.00	21.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,757.90	9,867.00	1,890.90	16.08
+ GST 7.00/0.00% (\$\$)	823.05	0.00	823.05	100.00
Nett Amount (\$\$)	12,580.95	9,867.00	2,713.95	21.57

INSPECTION

Date of Assignment: 25/01/2023 Present Location:

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 09/12/2022 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
Parts:	143	MERCEDES-BENZ CLA180 1.3 COUPE PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW3397K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER (WCP)	Buckled	740.00 F	*740.00 F
2	1		*1 PC FRT BUMPER CENTRE LOWER MOULDING (WCP)	Necessary	90.00 F	*90.00 F
3	1		*1 PC FRT BUMPER LOGO (WCP)	Necessary	48.00 F	*48.00 F
4	1		*1 PC FRT BUMPER LH SIDE RETAINER (WCP)	Cracked	15.00 F	*15.00 F
5	1		*1 PC FRT BUMPER CENTRE INNER GARNISH (WCP)	Cracked	88.00 F	*88.00 F
6	1		*2 PCS FRT BUMPER SIDE INNER TOP GARNISHS @39/PC (WCP)	Cracked	78.00 F	*94.00 F
7	1		*1 PC FRT BUMPER REINFORCEMENT (WCP)	Repair	280.00 F	*- F
8	1		*1 PC FRT BUMPER LH FOG LAMP GARNISH (WCP)	Dented	28.00 F	*25.00 F
9	1		*1 PC FRT BUMPER LH PARKING SENSOR (WCP)	Missing	108.00 F	*108.00 F
10	1		*1 PC FRT LH FENDER (WCP)	Bent	360.00 F	*330.00 F
11	1		*1 PC FRT LH FENDER INNER FRT BRACKET (WCP)	Missing	25.00 F	*35.00 F
12	1		*1 SET FRT LH FENDER INNER SHIELD (WCP)	Cracked	125.00 F	*125.00 F
13	1		*1 PC LH HEADLAMP (WCP)	Broken	1,615.00 F	*1,615.00 F
14	1		*1 PC LH HEADLAMP ECU (WCP)	Missing	330.00 F	*330.00 F
15	1		*1 PC LH HEADLAMP SOCKET WIRE HARNESS (WCP)	Serviceable	220.00 F	*- F
16	1		*1 PC FRT SUPPORT PANEL (WCP)	Cracked	328.00 F	*328.00 F
17	1		*1 PC FRT LH SPORT RIM (LOCAL REPAIR)	Dented	600.00 F	*250.00 FS
18	1		*1 PC FRT LH SHOCK ABSORBER (WCP)	Bent	420.00 F	*400.00 F
19	1		*1 PC FRT LH KNUCKLE ARM (WCP)	Bent	610.00 F	*610.00 F
20	1		*1 PC FRT LH LOWER ARM (WCP)	Distorted	410.00 F	*410.00 F
21	1		*1 PC FRT LH WHEEL BEARING (WCP)	Necessary	300.00 F	*300.00 F
22	1		*1 PC FRT LH SIDE MIRROR GLASS (WCP)	Broken	345.00 F	*188.00 F
23	1		*1 PC FRT LH SIDE MIRROR COVER (WCP)	Broken	135.00 F	*135.00 F
24	1		*1 PC FRT LH SIDE MIRROR HOUSING (WCP)	Broken	485.00 F	*485.00 F
25	1		*1 PC FRT LH SIDE MIRROR LEN (WCP)	Missing	106.00 F	*126.00 F
26	1		*RADIATOR TOP SHUTTER (WCP)	Cracked	-	*45.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)		7,889.00	6,920.00
+ Margin on L,N Items 10.00/10.00% (S\$)		788.90	667.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	8,677.90
						7,587.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT LH TYRE (40%)	350.00	140.00
Sub Total (\$\$)			350.00	140.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (KING DOLLY)	New	100.00	100.00
2	REMOVE & REFIX FRT BUMPER ASSY,FOG LAMPS,INNER GARNISH,FRT LH FENDER,HEADLAMP ASSY,SIDE MIRROR,TO KNOCK & REPAIR FRT LH FENDER INNER PANEL,RENEW FRT SUPPORT PANEL AND REALIGN THE SAME	New	800.00	600.00
3	REMOVE & REFIX FRT LH UNDER CARRIAGE,CHECK STEERING & PINION AND DRIVE	New	250.00	200.00
4	PUTTY & RESPRAY ON FRT BUMPER,FRT LH FENDER,FRT LH DOOR,BONNET,FRT LH WHEEL HOUSING	New	1,200.00	900.00
5	TO REMOVE & REFIX HEADLAMP WIRE SOCKET AND CHECK WIRING	New	100.00	80.00
6	TO RESET,RE-PROGRAMME ECU SYSTEM	New	200.00	200.00
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	80.00	60.00
Gross Labour Cost (\$\$)			2,730.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >