

Vehicle Damage Assessment Report for [SMW3397K]

Estimate Created: 08/03/2023 13:20 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 08/03/2023 16:01 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mercedes-Benz	Model	CLA
Engine Type			
License Plate Number	SMW3397K	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- MERCEDES BENZ CLA180 COUPE	Insurlogic 4 (08/03/2023 16:01)
- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$9,867.00 WITH 7 WORKING DAYS	Insurlogic 4 (08/03/2023 15:52)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRT BUMPER		1	740.00	10.00 %	814.00
FRT BUMPER CENTRE LOWER MOULDING		1	90.00	10.00 %	99.00
FRT BUMPER LOGO		1	48.00	10.00 %	52.80
FRT BUMPER LH SIDE RETAINER		1	15.00	10.00 %	16.50
FRT BUMPER CENTRE INNER GARNISH		1	88.00	10.00 %	96.80
FRT BUMPER SIDE INNER TOP GARNISHS		2	47.00	10.00 %	103.40
FRT BUMPER LH FOG LAMP GARNISH		1	25.00	10.00 %	27.50
RT BUMPER LH PARKING SENSOR		1	108.00	10.00 %	118.80
FRT LH FENDER		1	330.00	10.00 %	363.00
FRT LH FENDER INNER FRT BRACKET		1	35.00	10.00 %	38.50
FRT LH FENDER INNER SHIELD		1	125.00	10.00 %	137.50
LH HEADLAMP		1	1615.00	10.00 %	1,776.50
HEADLAMP ECU		1	330.00	10.00 %	363.00
RT SUPPORT PANEL		1	328.00	10.00 %	360.80
FRT LH SHOCK ABSORBER		1	400.00	10.00 %	440.00
FRT LH KNUCKLE ARM		1	610.00	10.00 %	671.00
FRT LH LOWER ARM		1	410.00	10.00 %	451.00
FRT LH WHEEL BEARING		1	300.00	10.00 %	330.00
RT LH SIDE MIRROR GLASS		1	188.00	10.00 %	206.80
FRT LH SIDE MIRROR COVER		1	135.00	10.00 %	148.50
FRT LH SIDE MIRROR HOUSING		1	485.00	10.00 %	533.50
LH SIDE MIRROR LEN		1	126.00	10.00 %	138.60
RADIATOR TOP SHUTTER		1	45.00	10.00 %	49.50

Parts Subtotal 7,337.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRT LH SPORT RIM		1.0	250.00	0.00 %	250.00
FRT LH TYRE		1.0	140.00	0.00 %	140.00

Materials Subtotal 390.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TOWING (KING DOLLY)	RnR	100.00	0.00 %	100.00
REMOVE & REFIX FRT BUMPER ASSY,FOG LAMPS,INNER GARNISH,FRT LH FENDER,HEADLAMP ASSY,SIDE MIRROR,TO KNOCK & REPAIR FRT LH FENDER INNER PANEL,RENEW FRT SUPPORT PANEL AND REALIGN THE SAME	RnR	600.00	0.00 %	600.00
REMOVE & REFIX FRT LH UNDER CARRIAGE,CHECK STEERING & PINION AND DRIVE	RnR	200.00	0.00 %	200.00
TO REMOVE & REFIX HEADLAMP WIRE SOCKET AND CHECK WIRING	RnR	80.00	0.00 %	80.00
TO RESET,RE-PROGRAMME ECU SYSTEM	RnR	200.00	0.00 %	200.00
TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	RnR	60.00	0.00 %	60.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PUTTY & RESPRAY ON FRT BUMPER,FRT LH FENDER,FRT LH DOOR,BONNET,FRT LH WHEEL HOUSING	Full spray	900.00	0.00 %	900.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,240.00

Paint Labor Subtotal 900.00

Labor Subtotal 2,140.00

Summary

Repair Cost 9,867.00

Discount(0 %) (0.00)

9,867.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 9,867.00