

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: ERGO Insurance Pte. Ltd. (HQ)

--

Singapore

Claimant Insurer: ERGO Insurance Pte. Ltd.**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	TP/ERGO(YP6157L)
Policy No:		Date of Loss:	03/12/2022
Vehicle Reg. No.:	SMW3397K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LEE SHIH HUI RACHEL (LI SIHUI)	Driver (Insured):	YANG YULU
Make/Model:	MERCEDES-BENZ CLA180, 1.3 COUPE PROGRESSIVE (A)	Vehicle Reg. Date:	16/11/2020
Vehicle Colour:	SILVER		
Engine No:	28291480397087	Chassis No:	W1K1183842N134816
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*Not authorised
Repair B4 paint
7 days
@ 9867.00*

COST OF CLAIMS

	Amount
Parts	8,677.90
Miscellaneous Items	350.00
Labour	2,730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	11,757.90
+ GST 7.00% (S\$)	823.05
Nett Amount (S\$)	12,580.95

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

SMW3397K
TP/ERGO

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2022)
Parts:	143	MERCEDES-BENZ CLA180 1.3 COUPE PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW3397K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC FRT BUMPER	Bu 0.00	0.00	*740.00 F	✓
2	1		*1 PC FRT BUMPER CENTRE LOWER MOULDING	Mu 0.00	0.00	*90.00 F	✓
3	1		*1 PC FRT BUMPER LOGO	Mu 0.00	0.00	*48.00 F	✓
4	1		*1 PC FRT BUMPER LH SIDE RETAINER	CM 0.00	0.00	*15.00 F	✓
5	1		*1 PC FRT BUMPER CENTRE INNER GARNISH	CM 0.00	0.00	*88.00 F	✓
6	1		*2 PCS FRT BUMPER SIDE INNER TOP GARNISHS @39/PC	CM 0.00	0.00	*78.00 F	94
7	1		*1 PC FRT BUMPER REINFORCEMENT	R 0.00	0.00	*280.00 F	x
8	1		*1 PC FRT BUMPER LH FOG LAMP GARNISH	25.00 0.00	0.00	*28.00 F	✓
9	1		*1 PC FRT BUMPER LH PARKING SENSOR	Mu 0.00	0.00	*108.00 F	✓
10	1		*1 PC FRT LH FENDER	330 Bu 0.00	0.00	*360.00 F	✓
11	1		*1 PC FRT LH FENDER INNER FRT BRACKET	35 Mu 0.00	0.00	*25.00 F	✓
12	1		*1 SET FRT LH FENDER INNER SHIELD	CM 0.00	0.00	*125.00 F	✓
13	1		*1 PC LH HEADLAMP	Bu 0.00	0.00	*1,615.00 F	✓
14	1		*1 PC LH HEADLAMP ECU	Mu 0.00	0.00	*330.00 F	✓
15	1		*1 PC LH HEADLAMP SOCKET WIRE HARNESS	Pu Mu 0.00	0.00	*220.00 F	x
16	1		*1 PC FRT SUPPORT PANEL	CM 0.00	0.00	*328.00 F	✓
17	1		*1 PC FRT LH SPORT RIM	6.1 250.00 Bu 0.00	0.00	*600.00 F	✓
18	1		*1 PC FRT LH SHOCK ABSORBER	Bu 400 0.00	0.00	*420.00 F	✓
19	1		*1 PC FRT LH KNUCKLE ARM	Bu 0.00	0.00	*610.00 F	✓
20	1		*1 PC FRT LH LOWER ARM	0.00 0.00	0.00	*410.00 F	✓
21	1		*1 PC FRT LH WHEEL BEARING	Mu 0.00	0.00	*300.00 F	✓
22	1		*1 PC FRT LH SIDE MIRROR GLASS	188 Bu 0.00	0.00	*345.00 F	✓
23	1		*1 PC FRT LH SIDE MIRROR COVER	Bu 0.00	0.00	*135.00 F	✓
24	1		*1 PC FRT LH SIDE MIRROR HOUSING	Bu 0.00	0.00	*485.00 F	✓
25	1		*1 PC FRT LH SIDE MIRROR LEN	126 Mu 0.00	0.00	*106.00 F	✓
						Sub Total (\$\$)	7,889.00
						+ Margin on L,N Items 10.00% (\$\$)	788.90
						Total Parts (\$\$)	8,677.90

F=Franchise part.

Radiator Top Shutter CM ✓ 45.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 PC FRT LH TYRE	140.00 Pu 40.00 350.00
			Sub Total (\$\$) 350.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TOWING (KING DOLLY)	New	(Bill) 100.00 ✓
2	REMOVE & REFIX FRT BUMPER ASSY,FOG LAMPS,INNER GARNISH,FRT LH FENDER,HEADLAMP ASSY,SIDE MIRROR,TO KNOCK & REPAIR FRT LH FENDER INNER PANEL,RENEW FRT SUPPORT PANEL AND REALIGN THE SAME	New	800.00 800 ✓
3	REMOVE & REFIX FRT LH UNDER CARRIAGE,CHECK STEERING & PINION AND DRIVE	New	200.00 250.00 ?
4	PUTTY & RESPRAY ON FRT BUMPER,FRT LH FENDER,FRT LH DOOR,BONNET,FRT LH WHEEL HOUSING	New	800.00 1,200.00
5	TO REMOVE & REFIX HEADLAMP WIRE SOCKET AND CHECK WIRING	New	80.00 100.00 ✓
6	TO RESET,RE-PROGRAMME ECU SYSTEM	New	200.00 ✓
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	80.00 60.00
Gross Labour Cost (\$\$)			2,730.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: