

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012297/RNP3E2**Date:** 15/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00121822202
Claimant Vehicle No :	SLR101E	Insured Vehicle No :	GBJ9867E
Date of Loss:	05/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D208742/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR101E	Engine No:	65492080107461
Make & Model:	MERCEDES-BENZ E200, 2.0 SE (A)	Chassis No:	WDD2130132A242082
Reg. Date:	12/10/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1950 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35Z R19	Rear Tyre Size:	275/35Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,629.60	11,725.60	1,904.00	13.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,770.00	3,660.00	1,110.00	23.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,399.60	15,385.60	3,014.00	16.38
+ GST 8.00/8.00% (S\$)	1,471.97	1,230.85	241.12	16.38
Nett Amount (S\$)	19,871.57	16,616.45	3,255.12	16.38

INSPECTION

Date of Assignment:	08/12/2022	
Date Inspected:	09/12/2022	Inspected At: AutoSprint Pte Ltd (HQ) 24, Leng Kee Road, #07-01/02 Leng Kee AutoPoint Singapore 159096
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2023)
Parts:	143	MERCEDES-BENZ E200 2.0 SE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR101E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Bent	2,000.00 F	*2,000.00 F
2	1		*REAR BOOT RUBBER	Necessary	240.00 F	*240.00 F
3	1		*REAR BOOT MOULDING	Cracked	160.00 F	*160.00 F
4	1		*REAR BOOT INNER LOCK	Cut	280.00 F	*280.00 F
5	1		*REAR BOOT COVER STAR EMBLEM	Necessary	56.00 F	*56.00 F
6	1		*REAR BOOT COVER E300 EMBLEM	Necessary	112.00 F	*112.00 F
7	2		*REAR BOOT INNER HINGE COVERS	Cut	180.00 F	*180.00 F
8	1		*REAR BOOT SURROUNDING GARNISH	Not Necessary	256.00 F	*- F
9	1		*REAR BOOT COVER INNER TRIM	Deformed	560.00 F	*560.00 F
10	1		*REAR BUMPER	Deformed	1,680.00 F	*1,680.00 F
11	1		*REAR BUMPER LOWER	Scratched	304.00 F	*304.00 F
12	1		*REAR BUMPER REINFORCEMENT	Bent	720.00 F	*720.00 F
13	2		*REAR BUMPER SENSORS	Distorted	338.00 F	*338.00 F
14	1		*REAR BUMPER RIVETS	Necessary	120.00 F	*120.00 F
15	2		*REAR TAIL LAMPS	Cracked	1,440.00 F	*1,440.00 F
16	2		*REAR TAIL LAMP BRACKETS	Cracked	160.00 F	*160.00 F
17	1		*REAR EXHAUST CHROME RIMS	O/S Scratched	320.00 F	*160.00 F
18	2		*REAR BOOT COVER HINGES	Cut	496.00 F	*496.00 F
19	2		*REAR BOOT COVER RUBBER STOPPER	Necessary	32.00 F	*32.00 F
20	1		*REAR END LOWER PANEL	Repair	1,440.00 F	*- F
21	1		*REAR BOOT AUTO OPENING MOTOR	Shorted	880.00 F	*880.00 F
22	1		*REAR BOOT COVER LOWER INNER LOCK ASSY	Cut	400.00 F	*400.00 F
23	1		*REAR BUMPER INNER TOP PLASTIC BEAM	Cracked	136.00 F	*136.00 F
24	2		*REAR BUMPER MOUNTINGS	Cracked	134.00 F	*134.00 F
25	1		*REAR BOOT LOWER LOCK MOTOR	Shorted	160.00 F	*160.00 F
26	1		*REAR BOOT INNER CONTROL UNIT	Shorted	480.00 F	*480.00 F
27	1		*REAR BOOT INNER CARPET RETAINING CLIPS	Necessary	24.00 F	*24.00 F
28	1		*REAR BOOT INNER CONTROL FUSE	Shorted	9.60 F	*9.60 F
29	1		*REAR BUMPER REFLECTORS	N/S NotNecessary/O/S Scratched	96.00 F	*48.00 F
30	1		*REAR BOOT CENTRE INNER PLASTIC TRIM	Cracked	416.00 F	*416.00 F

F=Franchise part.

Total Parts (S\$) 13,629.60 11,725.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO STRAIGHTEN & ALIGN LOWER END PANEL, REMOVE & REPLACE THE ABOVE LISTED DAMAGED PARTS	New	2,200.00	1,600.00
2	LABOUR CHARGE TO RECONNECT REAR LAMP WIRE HARDNESS, CODING & REPROGRAMMING SYSTEMS	New	450.00	200.00
3	LABOUR CHARGES TO REMOVE & REINSTALL REAR BOOT INNER TRIMMINGS & ATTACHMENT TO FACILITATE REPAIR WORKS	New	120.00	60.00
4	LABOUR CHARGE TO PUTTY & RESPRAY PAINTING SAME (5 PORTIONS)	New	2,000.00	1,800.00
Gross Labour Cost (S\$)			4,770.00	3,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >