

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012299/TVP3Q2**Date:** 16/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00128232202

Claimant Vehicle No : SLR7149Y **Insured Vehicle No :** GBK7833K

Date of Loss: 06/12/2022 Nature of Claim: TP Claim No: SNM22D208795/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR7149Y**

Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UGA6992

Reg. Date: 25/08/2017 (Man. Year: 2017) Chassis No: MMBSTA13AHH005494

Colour: White Odometer: 59505 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,390.50	4,764.70	5,625.80	54.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,700.00	1,550.00	5,150.00	76.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,090.50	6,314.70	10,775.80	63.05
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	17,090.50	5,050.00	12,040.50	70.45
+ GST 8.00/8.00% (S\$)	1,367.24	404.00	963.24	70.45
Nett Amount (S\$)	18,457.74	5,454.00	13,003.74	70.45

INSPECTION

Date of Assignment: 08/12/2022

Date Inspected: 09/12/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2023)
Parts:	143	mitsubishi attrage 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR7149Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	858.00 FL	*858.00 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	53.00 FL	*53.00 FL
3	1		*BOOTLID ATTRAGE EMBLEM	Necessary	21.00 FL	*21.00 FL
4	1		*BOOTLID MIVEC EMBLEM	Necessary	43.00 FL	*43.00 FL
5	1		*BOOTLID CHROME MOULDING	Cracked	318.00 FL	*318.00 FL
6	1		*SET BOOTLID CHROME MOULDING CLIPS	Necessary	50.00 FL	*20.00 FL
7	1		*BOOTLID RH HINGE	Not Necessary	192.00 FL	*- FL
8	1		*BOOTLID LH HINGE	Not Necessary	192.00 FL	*- FL
9	1		*BOOTLID LOCK	Bent	208.00 FL	*208.00 FL
10	1		*BOOTLID LOCK CATCH	Not Necessary	68.00 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Not Necessary	178.00 FL	*- FL
12	1		*REAR BUMPER	Deformed	654.00 FL	*654.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
14	1		*REAR BUMPER RH RETAINER	Not Necessary	32.00 FL	*- FL
15	1		*REAR BUMPER LH RETAINER	Deformed	32.00 FL	*32.00 FL
16	1		*REAR BUMPER LH REFLECTOR	Not Necessary	41.00 FL	*- FL
17	1		*REAR BUMPER RH REFLECTOR	Not Necessary	41.00 FL	*- FL
18	1		*LH TAILLAMP ASSY	Cracked	402.00 FL	*402.00 FL
19	1		*LH TAILLAMP PANEL	Not Necessary	98.00 FL	*- FL
20	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	22.00 FL	*- FL
21	1		*RH TAILLAMP ASSY	Cracked	402.00 FL	*402.00 FL
22	1		*RH TAILLAMP PANEL	Not Necessary	98.00 FL	*- FL
23	1		*SET RH TAILLAMP LOCK CLIPS	Not Necessary	22.00 FL	*- FL
24	1		*END PANEL	Bent	455.00 FL	*455.00 FL
25	1		*END PANEL INNER GARNISH	Deformed	89.00 FL	*89.00 FL
26	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
27	1		*END PANEL AIR VENT	Not Necessary	39.00 FL	*- FL
28	1		*END PANEL AIR VENT COVER	Not Necessary	53.00 FL	*- FL
29	1		*END PANEL RH SIDE COVER	Not Necessary	28.00 FL	*- FL
30	1		*END PANEL ANTENNA SENSOR	Not Necessary	101.00 FL	*- FL
31	1		*END PANEL BUZZER SENSOR	Cracked	95.00 FL	*95.00 FL
32	1		*LH REAR FENDER	Bent	808.00 FL	*808.00 FL
33	1		*LH REAR FENDER INNER TRIM BOARD	Torn	233.00 FL	*233.00 FL
34	1		*SET LH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	45.00 FL	*- FL
35	1		*LH REAR FENDER SPLASH SHIELD	Not Necessary	55.00 FL	*- FL
36	1		*SET LH REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
37	1		*RH REAR FENDER	Not Necessary	808.00 FL	*- FL
38	1		*RH REAR FENDER INNER TRIM BOARD	Not Necessary	233.00 FL	*- FL
39	1		*SET RH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	45.00 FL	*- FL
40	1		*RH REAR FENDER SPLASH SHIELD	Not Necessary	55.00 FL	*- FL
41	1		*SET RH REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
42	1		*SPARE TYRE PANEL	Not Necessary	923.00 FL	*- FL
43	1		*SPARE TYRE PANEL MAT	Not Necessary	198.00 FL	*- FL
44	1		*SPARE TYRE PANEL TOP COVER	Deformed	339.00 FL	*212.00 FL
45	1		*SPARE TYRE PANEL INSULATOR	Not Necessary	187.00 FL	*- FL
46	1		*EXHAUST SILENCER	Not Necessary	598.00 FL	*- FL

Report was unsubmitted during this print-out.

5/16/23, 1:20 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*EXHAUST SILENCER GASKET	Not Necessary	36.00 FL	*- FL
48	1		*EXHAUST SILENCER HANGERS	Not Necessary	67.00 FL	*- FL
49	1		*BOOTLID C&C EMBLEM	Necessary	85.00 FS	*85.00 FS
50	1		*BOOTLID SEAL	Not Necessary	60.00 FS	*- FS
51	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*40.00 FS
52	1		*SPARE TYRE PANEL JOINT SEALANT	Not Necessary	80.00 FS	*- FS
53	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	320.00 FS	*200.00 FS
54	1		*REAR REVERSE CAMERA	Not Necessary	780.00 FS	*- FS
55	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
56	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	70.00 FS	*- FS
57	1		*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS
58	1		*RH TAILLAMP PANEL JOINT SEALANT	Not Necessary	40.00 FS	*- FS
59	1		*LH TAILLAMP PANEL JOINT SEALANT	Not Necessary	40.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					11,360.00	5,258.00
- List Item Discount on L Items 10.00/10.00% (S\$)					969.50	493.30
Total Parts (S\$)					10,390.50	4,764.70
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK REPLACE AND INSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	2,400.00	700.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	2,000.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	30.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
6	REMOVE AND REPLACE REAR INNER TRIMS GARNISH AND BOARDS TO ASSIST REPAIR	New	350.00	60.00
7	REMOVE AND REPLACE EXHAUST SILENCER AND HANGERS TO ASSIST REPAIR	New	180.00	0.00
8	REMOVE AND REPLACE REAR REVERSE CAMERA TO ASSIST REPAIR	New	120.00	0.00
9	REMOVE AND REINSTALL ROOF LINING SEATS AND CARPET TO ASSIST REPAIR	New	480.00	0.00
10	MOUNT VEHICLE ON CHASSIS ALIGNMENT BENCH TO REPAIR CHASSIS FRAMES	New	650.00	0.00
11	REMOVE AND REINSTALL FUEL TANK PIPES ,HOSES AND SENSORS TO ASSIST REPAIR	New	220.00	0.00
Gross Labour Cost (\$\$)			6,700.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >