

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012302/KQP3Q2**Date:** 21/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00141582202
Claimant Vehicle No :	SLN3742G	Insured Vehicle No :	SMA8783L
Date of Loss:	06/12/2022	Nature of Claim: TP	Claim No: SNM22D208769/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN3742G	Engine No:	P520352178
Make & Model:	MAZDA 2, 1.5 SEDAN L SP.6EAT (A)	Chassis No:	MM6DL2SAAGW197038
Reg. Date:	28/04/2017 (Man. Year: 2016)	Odometer:	231266 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R16	Rear Tyre Size:	185/60 R16
Front Left Side:	Toyo 4 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,755.00	2,780.00	-1,025.00	-58.40
Miscellaneous Items	200.00	200.00	0.00	0.00
Labour	697.20	600.60	96.60	13.86
Paintwork Labour	739.93	850.85	-110.92	-14.99
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,392.13	4,431.45	-1,039.32	-30.64
+ GST 7.00/8.00% (S\$)	237.45	354.52	-117.07	-49.30
Nett Amount (S\$)	3,629.58	4,785.97	-1,156.39	-31.86

INSPECTION

Date of Assignment:	08/12/2022	Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	09/12/2022	Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	9.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	143	MAZDA 2 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3742G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		1,755.00 F	*2,780.00 F
F=Franchise part.						
Total Parts (S\$)					1,755.00	2,780.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	200.00	200.00
Sub Total (\$\$)			200.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	739.93	850.85
<u>Labour Items</u>				
2	Total of Labour	New	697.20	600.60
Gross Labour Cost (\$\$)			1,437.13	1,451.45

Report was unsubmitted during this print-out.

< END OF ESTIMATES >