

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012303/ANP3Q2**Date:** 29/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00219712201
<b>Claimant Vehicle No :</b>	SLV7411T	<b>Insured Vehicle No :</b>	SMV9834G
Date of Loss:	07/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D208814/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SLV7411T	Engine No:	G4FGHU127540
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHD841CMJU612134
Reg. Date:	13/01/2018 (Man. Year: 2017)	Odometer:	55500 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,262.00	5,119.36	3,142.64	38.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	2,000.00	1,750.00	46.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,012.00</b>	<b>7,119.36</b>	<b>4,892.64</b>	<b>40.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,012.00</b>	<b>5,700.00</b>	<b>6,312.00</b>	<b>52.55</b>

**INSPECTION**

Date of Assignment:	08/12/2022	
Date Inspected:	08/12/2022 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV7411T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	1,977.80 FL	*1,782.00 FL
2	1		*REAR BOOTLID INNER LOWER RUBBER	Necessary	75.00 FL	*75.00 FL
3	2		*REAR BOOTLID HINGE	Not Necessary	207.40 FL	*- FL
4	1		*REAR BOOTLID UPPER LOCK	Damaged	139.30 FL	*139.30 FL
5	1		*REAR BOOTLID LOWER CATCH	Not Necessary	138.80 FL	*- FL
6	1		*REAR BOOTLID WEATHERSTRIP	Cut	101.80 FL	*101.80 FL
7	1		*REAR BOOTLID INSULATION	Not Necessary	161.50 FL	*- FL
8	1		*REAR BOOTLID CENTRE LOGO	Necessary	52.80 FL	*52.80 FL
9	1		*REAR BOOTLID ELANTRA EMBLEM	Necessary	63.80 FL	*63.80 FL
10	1		*REAR BOOTLID S EMBLEM	Necessary	22.00 FL	*22.00 FL
11	2		*REAR BOOTLID REFLECTOR	Cut	682.00 FL	*682.00 FL
12	2		*REAR LAMP	Cracked	1,581.60 FL	*1,196.00 FL
13	2		*REAR LAMP HOUSING	Repair	1,896.40 FL	*- FL
14	1		*REAR END PANEL	Dented	525.00 FL	*525.00 FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	76.80 FL	*76.80 FL
16	1		*REAR BUMPER	Deformed	505.80 FL	*505.80 FL
17	2		*REAR BUMPER SIDE HOLDER	Damaged	61.60 FL	*61.60 FL
18	2		*REAR BUMPER LOWER REFLECTOR	Cracked	73.60 FL	*73.60 FL
19	1		*REAR BUMPER LOWER LIP	Deformed	308.00 FL	*308.00 FL
20	1		*REAR BUMPER REINFORCEMENT	Bent	324.30 FL	*324.30 FL
21	2		*REAR BUMPER BRACKET	Not Necessary	121.80 FL	*- FL
22	1		*REAR BUMPER SPONGE	Not Necessary	194.00 FL	*- FL
23	1		*REAR BUMPER TOP BRACKET	Not Necessary	22.00 FL	*- FL
24	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	380.00 FL	*- FL
25	1		*REAR ANTENNA SENSOR	Cracked	159.40 FL	*159.40 FL
26	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,232.50	6,349.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,970.50	1,229.84
Total Parts (\$\$)	8,262.00	5,119.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SUPPLY REAR END PANEL INNER SEAL	New	200.00	80.00
2	REMOVE & REINSTALL REVERSE SENSOR	New	200.00	50.00
3	REMOVE & REINSTALL BOOTLID INNER GARNISH	New	200.00	80.00
4	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,500.00	800.00
5	RESPRAY PAINTING	New	1,300.00	800.00
6	TO APPLY TUFF COAT	New	150.00	80.00
7	TO REMOVE AND REINSTALL REAR CAMERA	New	100.00	50.00
8	TO SEND VEHICLE FOR WEEKEND CAR PLATE INSPECTION	New	100.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>3,750.00</b>	<b>2,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >