

# HUA MENG SPRAY PAINTING WORKSHOP

the Repairer of the following:

- To repair and respray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

Vehicle No : SLV7411T

Make/Model : HYUNDAI ELANTRA

Chassis No: KMHD841CMJU612134

Accident date : 07.12.2022

| No | Signature | DESCRIPTION | Qty | Amount (\$\$) |
|----|-----------|-------------|-----|---------------|
|----|-----------|-------------|-----|---------------|

### List Items

|               |                                       |           |   |             |       |
|---------------|---------------------------------------|-----------|---|-------------|-------|
| 1             | Rear bootlid                          | Dented.   | 1 | \$ 1,977.80 | 1782. |
| 2             | Rear bootlid inner lower rubber       | new       | 1 | \$ 75.00    |       |
| 3             | Rear bootlid hinge @ \$103.70         | new       | 2 | \$ 207.40   | X     |
| 4             | Rear bootlid upper lock               | Damaged   | 1 | \$ 139.30   | X     |
| 5             | Rear bootlid lower catch              | new       | 1 | \$ 138.80   | X     |
| 6             | Rear bootlid weather strip            | new       | 1 | \$ 101.80   |       |
| 7             | Rear bootlid insulation               | new       | 1 | \$ 161.50   | +     |
| 8             | Rear bootlid centre logo              |           | 1 | \$ 52.80    | -     |
| 9             | Rear bootlid "Elantra" emblem         | new       | 1 | \$ 63.80    | -     |
| 10            | Rear bootlid "S" emblem               |           | 1 | \$ 22.00    | -     |
| 11            | Rear bootlid reflector @ \$341.00     | at        | 2 | \$ 682.00   | -     |
| 12            | Rear lamp @ \$790.80                  | cracked.  | 2 | \$ 1,581.60 | 1186. |
| 13            | Rear lamp housing @ \$948.20          | Repair    | 2 | \$ 1,896.40 | X     |
| 14            | Rear end panel                        | Dented.   | 1 | \$ 525.00   | -     |
| 15            | Rear end panel top garnish            | Deformed  | 1 | \$ 76.80    | -     |
| 16            | Rear bumper                           | Deformed  | 1 | \$ 505.80   | -     |
| 17            | Rear bumper side holder @ \$30.80     | and       | 2 | \$ 61.60    | -     |
| 18            | Rear bumper lower reflector @ \$36.80 | cracked.  | 2 | \$ 73.60    | X     |
| 19            | Rear bumper lower lip                 | Deformed. | 1 | \$ 308.00   | -     |
| 20            | Rear bumper reinforcement             | Best.     | 1 | \$ 324.30   | -     |
| 21            | Rear bumper bracket @ \$60.90         | new       | 2 | \$ 121.80   | X     |
| 22            | Rear bumper sponge                    |           | 1 | \$ 194.00   | X     |
| 23            | Rear bumper top bracket               | new       | 1 | \$ 22.00    | X     |
| 24            | Rear spare tyre top board             |           | 1 | \$ 380.00   | X     |
| 25            | Rear Antenna Sensor                   | cracked.  |   | \$ 9,693.10 |       |
| Less 20% Disc |                                       |           |   | \$ 1,938.62 |       |
| Total         |                                       |           |   | \$ 7,754.48 |       |

### Special Nett Items

|       |                                    |             |   |           |      |
|-------|------------------------------------|-------------|---|-----------|------|
| 1     | Rear bumper reverse sensor (1 set) | Damaged 200 | 1 | \$ 380.00 | 200. |
| Total |                                    |             |   | \$ 380.00 |      |

### Labour Cost

|                                                       |      |    |                         |
|-------------------------------------------------------|------|----|-------------------------|
| 1 To supply rear end panel inner seal                 |      | \$ | <del>200.00</del> 80.   |
| 2 Remove & reinstall reverse sensor                   | 2000 | \$ | <del>200.00</del> 50    |
| 3 Remove & reinstall bootlid inner garnish            |      | \$ | <del>200.00</del> 80.   |
| 4 Remove ,replace & repair consistent to the accident |      | \$ | <del>1,500.00</del> 80  |
| 5 Respray painting                                    |      | \$ | <del>1,300.00</del> 80. |
| 6 To apply tuff coat                                  | 150  | \$ | <del>150.00</del> 80.   |
|                                                       |      | \$ | <del>3,400.00</del>     |
|                                                       |      | \$ | <del>3,400.00</del>     |

|             |                                                  |         |  |              |  |
|-------------|--------------------------------------------------|---------|--|--------------|--|
| 7           | To remove and reinstall rear camera.             | 150 80. |  |              |  |
| 8           | To send vehicle for weekend car plate inspection | 100 50  |  |              |  |
| Grand Total |                                                  |         |  | \$ 11,534.48 |  |

total: 7119.36  
9/5/ 5-7K. 06 Days