



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EU 240D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER FOR BUMPER PRIMED (SN)	TO REPAIR SEE LABOUR	1,486.06	-
1	SENSOR BRACKET (SN)	NOT NECESSARY	13.54	-
2	SENSOR BRACKET @\$13.54 (SN)	NOT NECESSARY	27.08	-
1	SENSOR BRACKET (SN)	NOT NECESSARY	13.54	-
1	2K-PLASTIC ADHESIVE (SN)	NOT NECESSARY	85.94	-
1	BONDING AGENT FOR PLASTIC (SN)	NOT NECESSARY	68.85	-
			1,695.01	-
<u>LABOUR</u>				
	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR.	NOT NECESSARY	280.00	-
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
	LABOUR. INCLUSIVE OF THE REPAIR OF COVER FOR BUMPER PRIMED.		1,680.00	840.00
	SPRAY PAINTING.		1,600.00	800.00
			4,040.00	2,120.00
GRAND TOTAL			5,735.01	2,120.00
RECOMMENDED COST OF REPAIRS				2,120.00

Report Ref No. CS/FCI22012307/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.