

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	HSBC LIFE (SING	APORE) PTE LTD		Ref:	CS3/ASM22012308/Tvp3e2	
	10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 018		Date:	29/03/2023		
	ATTN: LOH CYNTH	AIA		Code:	HSB	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 8044D	Veh. Inspected		FBQ 5000D	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M04FWO	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		08/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA NMAX 155	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	MH3SG431000012963	Colour		GREY	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/70-13	PIRELLI		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	130/70-13	PIRELLI		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.					
5. General Information						
	Accident Date	02/12/2022	Inspect Date /	Time	09/12/2022 ( 12:00 PM )	
	Survey held at M 1 MOTORING					
	411 CHANGI ROAD SINGAPORE 419860					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM22012308/Tvp3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser