



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 5411R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE, REPLACE, REALIGN REFRIGERATED BOX LH SIDE PANEL AND REAR DOOR ALUMINIUM SUPPORT FRAME. (INCLUDE SUPPLY REFRIGERATED BOX LH SIDE PANEL, REAR DOOR ALUMINIUM SUPPORT FRAME AND SEALANTS). TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA. TO SUPPLY BODY STICKER (ADVERTISEMENT GRAPHICS) FILM MATERIALS AND WRAP, APPLY ON REFRIGERATED BOX LH SIDE PANEL.		2,500.00	1,500.00
			1,200.00	500.00
			1,200.00	700.00
			4,900.00	2,700.00
GRAND TOTAL			4,900.00	2,700.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,150.00

Report Ref No. CS3/LPC22007111/Rny3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.