

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22007111/Rcy3e2
	300 BEACH ROAD SINGAPORE 1995		Date:	22/08/2022	
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YN 4109A	Veh. Inspected		GV 5411R
	Policy No.		Coverage (\$)		0.00
	Claim No.	21/22/22/VC05/026065	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		26/07/2022
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA	c.c		2982
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	JTFAT35YX0K210547	Colour		WHITE
	Odometer	113128 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195 R15C	MICHELIN		7 mm
	L/H Front Tyre	195 R15C	MICHELIN		7 mm
	R/H Rear Tyre	155 R12C (D)	LINAM		5/5 mm
	L/H Rear Tyre	155 R12C (D)	LINAM		5/5 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S BODY.			
5.	General Information				
	Accident Date	22/07/2022	Inspect Date /	Time	27/07/2022 (02:21 PM)
	Survey held at	SHENG KHOON MOTOR SERVICE			
		393 WOODLANDS ROAD BLK D4 YEE TEE INDUSTRIAL ESTATE SINGAPORE 677972			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22007111/Rcy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser