7/18/23, 3:16 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB22012313/NYA3Q2

**Date:** 18/07/2023

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01

Claimant Vehicle SH9408G Insured Vehicle No: SMV6258P

No:

Date of Loss: 06/12/2022 Nature of Claim: TP Claim No: MFL2022D0010971

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SH9408G

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEJU192066

Reg. Date: 02/04/2019 (Man. Year: 2018) Chassis No: KMHC851CVKU141569

Colour: Blue Odometer: 443196 km

Engine Capacity: 1580 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,073.12	1,688.24	384.88	18.57
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	750.00	630.00	120.00	16.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	2,834.12	2,329.24	504.88	17.81
Approved Total (Overridden) (S\$	)	1,850.00		
(\$\$	2,834.12	1,850.00	984.12	34.72
+ GST 7.00/7.00% (S\$	) 198.39	129.50	68.89	34.72
Nett Amount (S\$	3,032.51	1,979.50	1,053.01	34.72
+ Loss of Use (4.0	x S\$40.00/day) (S\$)	160.00		
+ Car Rental (4.0 )	x S\$125.19/day) (S\$)	500.76		
	(S\$)	2,640.26		
Liable A	mount (50.00%) (S\$)	1,320.13		
1+	Doc/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	1,327.58		

**INSPECTION** 

Date of Assignment: 09/12/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 08/12/2022 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jan 2023)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH9408G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Repair	481.10 FL	*- FL
2	1		*HEADLAMP ASSY RH	Scratched	2,110.30 FL	*2,110.30 FL
F=Fra	nchise	part. L=ListItemD	lisc.	-		
				Sub Total (S\$)	2,591.40	2,110.30
			- List Item Discount o	- List Item Discount on L Items 20.00/20.00% (S\$)		422.06
				Total Parts (S\$)	2,073.12	1,688.24
			Report was unsi	ubmitted during this print-out.		

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Misc	cellan	neous Items			,
1	1	OD/TP Case (Insurer)		11.00	11.00
			Sub Total (S\$)	11.00	11.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	CHECK WIRING	New	50.00	30.00
		Gross Labour Cost (S\$)	750.00	630.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >