

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012320/UYA3Q2**Date:** 17/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070138660
Claimant Vehicle No :	SJQ9143D	Insured Vehicle No :	GBG3170L
Date of Loss:	08/12/2022	Nature of Claim:	TP
		Claim No:	8253353463SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ9143D	Engine No:	L13Z11704869
Make & Model:	HONDA JAZZ, 1.3 (A)	Chassis No:	MRHGE68509P022180
Reg. Date:	29/05/2009 (Man. Year: 2009)	Odometer:	563198 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,878.56	5,446.96	6,431.60	54.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,140.00	2,390.00	2,750.00	53.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,018.56	7,836.96	9,181.60	53.95
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	17,018.56	6,250.00	10,768.56	63.28
+ GST 8.00/8.00% (S\$)	1,361.48	500.00	861.48	63.28
Nett Amount (S\$)	18,380.04	6,750.00	11,630.04	63.28
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,177.45		

INSPECTION

Date of Assignment:	09/12/2022	MG Solution Pte Ltd (HQ)
Date Inspected:	09/12/2022 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Badly Dented	956.40 FL	*932.90 FL
2	1		*TAIL GATE LOGO	Necessary	74.50 FL	*38.00 FL
3	2		*TAIL GATE DAMPER	Not Necessary	650.00 FL	*- FL
4	2		*TAIL GATE HINGE	Not Necessary	180.00 FL	*- FL
5	4		*TAIL GATE STOPPER	Not Necessary	144.80 FL	*- FL
6	1		*TAIL GATE INNER HANDLE	Serviceable	103.50 FL	*- FL
7	1		*TAIL GATE INNER LOCK	Dented / Damaged	256.00 FL	*223.80 FL
8	1		*TAIL GATE CATCH	Not Necessary	68.50 FL	*- FL
9	1		*TAIL GATE WEATHER STRIP	Twisted	224.00 FL	*92.30 FL
10	1		*TAIL GATE INNER TRIM BOARD	Deformed / Torn	562.00 FL	*114.60 FL
11	1		*TAIL GATE WINDSCREEN	Shattered	822.30 FL	*640.10 FL
12	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	164.00 FL	*60.00 FL
13	1		*TAILGATE WIPER MOTOR	Bent / Jammed	328.40 FL	*238.60 FL
14	1		*TAIL GATE WIPER	Not Necessary	146.50 FL	*- FL
15	1		*REAR BUMPER	Distorted	550.00 FL	*440.30 FL
16	2		*REAR BUMPER SIDE RETAINER	Bent	124.60 FL	*50.00 FL
17	1		*REAR BUMPER BRACKET	O/S Dented	180.00 FL	*90.00 FL
18	1		*REAR BUMPER TOWING COVER	Torn	80.00 FL	*20.00 FL
19	1		*NUMBER PLATE GARNISH	Cracked	211.30 FL	*136.30 FL
20	1		*SET NUMBER PLATE LAMP	Not Necessary	110.50 FL	*- FL
21	2		*TAIL LAMP	Cracked	713.80 FL	*412.40 FL
22	2		*TAIL LAMP LOWER BRACKET	Not Necessary	104.80 FL	*- FL
23	1		*TAIL LAMP PANEL	N/S Repair / O/S Dented	306.00 FL	*153.00 FL
24	2		*REAR FENDER	Repair	1,421.00 FL	*- FL
25	2		*REAR FENDER INNER TRIM	Deformed / Torn	977.00 FL	*377.80 FL
26	2		*REAR FENDER QUARTER GLASS MOULDING	Not Necessary	210.40 FL	*- FL
27	1		*REAR END PANEL	Badly Dented	524.60 FL	*325.00 FL
28	1		*REAR END PANEL TOP GARNISH	Twisted	163.50 FL	*80.60 FL
29	1		*FLOOR PANEL	Crumpled	824.00 FL	*737.00 FL
30	1		*REAR FLOOR PANEL TOP BOARD	Torn	235.80 FL	*216.00 FL
31	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
32	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	22.00 FS	*22.00 FS
33	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*TAIL GATE WINDSCREEN SOLAR FILM	Necessary	250.00 FS	*150.00 FS
35	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
36	1		*REAR BUMPER LOWER LID	Cracked	1,000.00 FS	*600.00 FS
37	2		*SET TAIL LAMP CLIP	Not Necessary	40.00 FS	*- FS
38	2		*TAIL LAMP PANEL SEALANT	Not Necessary	200.00 FS	*- FS
39	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
40	2		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
41	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*50.00 FS
42	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	180.00 FS	*- FS
43	1		*SET REVERSE SENSOR	Torn	220.00 FS	*200.00 FS
44	1		*REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
45	1		*PHV STICKER	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,162.20	6,522.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,283.64	1,075.74
Total Parts (\$\$)	11,878.56	5,446.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	20.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	150.00	80.00
6	REMOVE AND REFIX TAILGATE WINDSCREEN	New	150.00	120.00
7	TO TRANSFER TAILGATE MECHANISM	New	150.00	60.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING }	New	150.00	50.00
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING }	New	150.00	0.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
11	TO REMOVE AND REFIX REAR FUEL TANK	New	180.00	0.00
Gross Labour Cost (\$\$)			5,140.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >