

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012322/UYA3Q2**Date:** 17/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210149340
Claimant Vehicle No :	SLT1399X	Insured Vehicle No :	SND2381A
Date of Loss:	08/12/2022	Nature of Claim:	TP
		Claim No:	5434980975SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT1399X		
Make & Model:	TOYOTA SIENTA, 1.5 CVT STD (A)	Engine No:	2NRX222380
Reg. Date:	19/10/2017 (Man. Year: 2017)	Chassis No:	MHFZ28H3400043288
Colour:	Orange	Odometer:	109769 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,917.70	4,356.15	19,561.55	81.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,160.00	1,910.00	2,250.00	54.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,077.70	6,266.15	21,811.55	77.68
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	28,077.70	5,000.00	23,077.70	82.19
+ GST 7.00/7.00% (S\$)	1,965.44	350.00	1,615.44	82.19
Nett Amount (S\$)	30,043.14	5,350.00	24,693.14	82.19
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,852.00		

INSPECTION

Date of Assignment:	09/12/2022	
Date Inspected:	09/12/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,488.10 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	188.30 F	*110.80 FL
3	1		*TAILGATE	Badly Dented	1,885.10 F	*1,466.20 FL
4	1		*TAILGATE OUTER HANDLE	Not Necessary	344.80 F	*- FL
5	1		*TAILGATE REAR LOGO	Necessary	68.50 F	*68.50 FL
6	1		*TAILGATE SIENTA EMBLEM	Necessary	66.80 F	*66.80 FL
7	1		*TAILGATE G EMBLEM	Necessary	50.00 F	*50.00 FL
8	2		*TAILGATE REFLECTORS	Not Necessary	1,300.00 F	*- FL
9	1		*TAILGATE REAR WIPER ARM	Not Necessary	188.90 F	*- FL
10	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	620.00 F	*- FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	288.90 F	*288.90 FL
12	1		*TAILGATE INNER LOCK	Damaged	341.90 F	*341.90 FL
13	1		*TAILGATE LOCK STIRKER	Not Necessary	60.00 F	*- FL
14	1		*TAILGATE INNER TRIM	Not Necessary	311.60 F	*- FL
15	2		*TAILGATE DAMPERS	Not Necessary	598.00 F	*- FL
16	1		*TAILGATE INNER HOLDER GARNISH	Not Necessary	58.00 F	*- FL
17	1		*REAR BUMPER	Deformed / Torn	1,315.10 F	*720.10 FL
18	1		*REAR BUMPER CENTRE BLACK GARNISH	Grazed	488.90 F	*311.60 FL
19	2		*REAR BUMPER SIDE BLACK GARNISHS	Twisted / Grazed	570.20 F	*320.00 FL
20	2		*REAR BUMPER REFLECTORS	Not Necessary	170.00 F	*- FL
21	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FL
22	1		*REAR BUMPER SPONGE	Not fitted	199.80 F	*- FL
23	2		*REAR BUMPER PDC SENSORS	Shorted	570.00 F	*410.00 FL
24	1		*REAR END PANEL OUTER	Badly Dented / Bent	899.10 F	*699.50 FL
25	1		*REAR END PANEL INNER	Bent	688.10 F	*545.00 FL
26	1		*REAR END PANEL LOCK SENSOR	Not Necessary	350.00 F	*- FL
27	1		*REAR END PANEL TOP GARNISH	Twisted	168.90 F	*168.90 FL
28	2		*TAILLAMPS	Not Necessary	1,701.00 F	*- FL
29	2		*TAILLAMP HOUSING PANELS	Not Necessary	900.60 F	*- FL
30	1		*REAR FENDER	Not Necessary	1,205.10 F	*- FL
31	2		*REAR FENDER INNER TRIM BOARDS	Not Necessary	1,370.20 F	*- FL
32	1		*REAR FENDER OUTER TOP PROTECTOR N/S	Not Necessary	655.50 F	*- FL
33	1		*REAR FLOOR PANEL	Repair	1,415.10 F	*- FL
34	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	622.30 F	*- FL
35	1		*REAR FLOOR PANEL TOP TRAY	Not Necessary	588.10 F	*- FL
36	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	520.80 F	*- FL
37	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
38	1		*REAR BUMPER CENTRE LAMP	Not Necessary	150.00 FS	*- FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
40	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
41	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*40.00 FS
42	1		*SET TAILGATE INNER TRIM INSULATOR	Not Necessary	300.00 FS	*- FS
43	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	450.00 FS	*- FS
44	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,917.70	5,748.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,392.05
Total Parts (\$\$)	23,917.70	4,356.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR FENDER GLASS	New	100.00	0.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
8	TO SPRAY PROOFING	New	180.00	80.00
9	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,400.00	600.00
11	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (S\$)			4,160.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >