

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22012324/TWP3M4**Date:** 29/05/2023**REFERENCE**

Insured/Claimant:	SUYUN TANG	Policy No:	1800069536-04	
Date of Loss:	04/12/2022	Nature of Claim:	OD	Claim No: 5028916556SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJR3214S</b>		
Make & Model:	AUDI A3 SPORTBACK, 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZ464327
Reg. Date:	14/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V8JA115083
Colour:	Red	Odometer:	29174 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,121.00	7,906.88	3,214.12	28.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,462.00	6,387.00	3,075.00	32.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,583.00</b>	<b>14,293.88</b>	<b>6,289.12</b>	<b>30.55</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>19,983.00</b>	<b>13,693.88</b>	<b>6,289.12</b>	<b>31.47</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>1,598.64</b>	<b>1,095.51</b>	<b>503.13</b>	<b>31.47</b>
<b>Nett Amount (S\$)</b>	<b>21,581.64</b>	<b>14,789.39</b>	<b>6,792.25</b>	<b>31.47</b>

**INSPECTION**

Date of Assignment:	09/12/2022	
Date Inspected:	08/12/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SIDE PANEL - LH	Bent	4,445.00 FS	*3,556.00 FS
2	1		*REAR WHEEL SPOILER - LH	Not Necessary	39.00 FS	*- FS
3	1		*REAR WHEEL HOUSING LINER	Not Necessary	260.00 FS	*- FS
4	1		*REAR DOOR - LH	Bent	2,973.00 FS	*2,378.40 FS
5	1		*REAR OUTER DOOR SEAL - LH	Necessary	179.00 FS	*142.80 FS
6	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
7	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
8	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
9	1		*REAR DOOR CATCH - LH	Not Necessary	105.00 FS	*- FS
10	1		*REAR DOOR INNER SEAL - LH	Not Necessary	213.00 FS	*- FS
11	1		*REAR WINDOW REGULATOR - LH	Not Necessary	286.00 FS	*- FS
12	1		*REAR ALUMINIUM RIM	Cut	1,303.00 FS	*1,042.40 FS
13	1		*REAR ALUMINIUM RIM RUBBER VALVE	Necessary	4.00 FS	*2.96 FS
14	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
15	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
16	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
17	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
18	1		*LHS REAR TYRE (TBC) (NPA)	Not Necessary	0.00 FS	*- FS
19	1		*SUNDRIES	Necessary	400.00 FS	*4.32 FS
					<b>Total Parts (\$\$)</b>	<b>11,121.00      7,906.88</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	350.00
2	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
3	TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR LOWER SECTION FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	2,000.00
4	TO RESPRAY LHS REAR FENDER, LHS SILL PANEL, LHS REAR DOOR AND DOOR ENTRANCE	New	3,500.00	1,925.00
5	TO RENEW LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>9,462.00</b>	<b>6,387.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >