

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012325/AVP3Q2**Date:** 22/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00002502200
Claimant Vehicle No :	GBJ3480B	Insured Vehicle No :	SMU7495U
Date of Loss:	03/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D208736/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ3480B	Engine No:	1KD2837806
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y90K212323
Reg. Date:	28/03/2019 (Man. Year: 2018)	Odometer:	29073 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,877.67	3,756.52	2,121.15	36.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,570.00	890.00	36.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,337.67	5,326.52	3,011.15	36.12
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	8,337.67	4,200.00	4,137.67	49.63
+ GST 7.00/7.00% (S\$)	583.64	294.00	289.64	49.63
Nett Amount (S\$)	8,921.31	4,494.00	4,427.31	49.63

INSPECTION

Date of Assignment:	09/12/2022	
Date Inspected:	12/12/2022	Inspected At: 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 Repairer:N-51automotive Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Dec 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ3480B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	895.20 FL	*481.00 FL
2	2		*FRONT BUMPER FOGLAMP GARNISH RH	Cut	270.00 FL	*135.00 FL
3	2		*FRONT BUMPER INNER BRACKET RH	Bent	301.00 FL	*150.50 FL
4	1		*FRONT BUMPER INNER REINFORCEMENT	Not Necessary	182.20 FL	*- FL
5	1		*FRONT GRILLE	Cracked	595.20 FL	*595.20 FL
6	1		*FRONT GRILLE LOGO EMBLEM	Necessary	70.50 FL	*70.50 FL
7	1		*FRONT RH CORNER PANEL	Cracked	336.40 FL	*336.40 FL
8	1		*FRONT RH DOOR	Dented	1,794.20 FL	*1,485.00 FL
9	1		*FRONT RH DOOR CHECKER	Not Necessary	183.20 FL	*- FL
10	1		*FRONT RH DOOR HINGE (LOWER)	Bent	110.00 FL	*110.00 FL
11	1		*FRONT RH DOOR HINGE (TOP)	Not Necessary	110.00 FL	*- FL
12	1		*FRONT RH DOOR PILLAR (OUTER)	Repair	414.30 FL	*- FL
13	1		*FRONT RH DOOR WEATHERSTRIP	Not Necessary	243.70 FL	*- FL
14	1		*FRONT RH DOOR WEATHERSTRIP VERTICAL	Cut	115.30 FL	*115.30 FL
15	1		*FRONT RH HEADLAMP	Cut	892.90 FL	*727.00 FL
16	1		*FRONT RH STEP GARNISH	Cut	302.80 FL	*302.80 FL
17	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	25.00 FS	*- FS
18	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
19	1		*FRONT RH DOOR 3D STICKER	Necessary	600.00 FS	*320.00 FS
20	1		*FRONT RH DOOR COMPANY STICKER	Necessary	25.00 FS	*25.00 FS
21	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
22	1		*SET FRONT RH HEADLAMP CLIPS	Necessary	25.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,581.90	4,883.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,704.23	1,127.18
Total Parts (\$\$)	5,877.67	3,756.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	80.00	30.00
2	TO TRANSFER DOOR GLASS ,REGULATOR GEAR,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	80.00	80.00
3	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
4	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
Gross Labour Cost (\$\$)			2,460.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >