



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7770P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	BUCKLED	591.75	591.75
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER HOLE COVER RH	SERVICEABLE	28.38	-
1	FRONT FENDER RH	DENTED	1,111.93	1,111.93
1	FRONT FENDER (HYBRID) RH	NECESSARY	86.50	86.50
1	FRONT FENDER SHIELD RH	SERVICEABLE	198.50	-
1	FRT BUMPER GRILLE RH	SCRATCHED	93.45	93.45
	LESS 25% DISCOUNT		-533.13	-476.41
			1,599.38	1,429.22
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		40.00	30.00
			1,440.00	1,230.00
	GRAND TOTAL		3,039.38	2,659.22
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,659.22

Report Ref No. NS/INC22012327/Nvp3m4

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.