

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012336/UYA3Q2**Date:** 13/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900096148-03
Claimant Vehicle No :	SBB5445H	Insured Vehicle No :	SGD2622M
Date of Loss:	08/12/2022	Nature of Claim:	TP
		Claim No:	9623220955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBB5445H	Engine No:	G4FGHU620961
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU543328
Reg. Date:	23/09/2017 (Man. Year: 2017)	Odometer:	77338 km
Colour:	Beige		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,717.60	3,312.00	2,405.60	42.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,660.00	740.00	30.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,117.60	4,972.00	3,145.60	38.75
+ GST 7.00/7.00% (S\$)	568.23	348.04	220.19	38.75
Nett Amount (S\$)	8,685.83	5,320.04	3,365.79	38.75
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
Nett Liability (S\$)		5,570.04		

INSPECTION

Date of Assignment:	09/12/2022		
Date Inspected:	19/12/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Badly Dented	1,993.00 FL	*1,993.00 FL
2	1		*REAR LH DOOR	Badly Dented	2,147.00 FL	*2,147.00 FL
3	1		*REAR LH DOOR HINGE -UPPER	Not Necessary	49.00 FL	*- FL
4	1		*REAR LH DOOR HINGE -LOWER	Not Necessary	49.00 FL	*- FL
5	1		*REAR LH DOOR POWER WINDOW REGULATOR	Not Necessary	229.00 FL	*- FL
6	1		*REAR LH DOOR POWER WINDOW REGULATOR MOTOR	Not Necessary	188.00 FL	*- FL
7	1		*REAR LH DOOR TRIMBOARD	Not Necessary	693.00 FL	*- FL
8	1		*REAR LH FENDER (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR LH ROCKER PANEL	Repair	1,799.00 FL	*- FL
10	1		*REAR LH DOOR PILLAR (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,147.00	4,140.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,429.40	828.00
Total Parts (\$\$)	5,717.60	3,312.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	1,200.00	900.00
2	LABOUR CHARGE	New	980.00	600.00
3	TUFF COAT	New	100.00	60.00
4	WIRING ,REMOVE & REFIX DOOR REGULATOR	New	120.00	100.00
Gross Labour Cost (\$\$)			2,400.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >