

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INSI	PECTION REPOR	PT	
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM22012342/Rwp3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Date	e: 15/12/2022	
	ATTN: ANG YVON	NE	Cod	e: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 8493H	Veh. Inspected	FBT 6693G	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S2M04G4I	Excess (\$)	0.00	
	Assign From	ANG YVONNE	Assign Date	09/12/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	YAMAHA XMAX 300 ABS CVT	c.c	292	
	Engine No.	HIDDEN	Year of Reg.	2022	
	Chassis No.	MH3SH182111015907	Colour	MULTI COLOUR	
	Odometer	23828 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	120/70-15	PIRELLI	6 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	140/70-14	PIRELLI	6 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
5.	General Information				
	Accident Date	06/12/2022	Inspect Date / Time	12/12/2022 ( 12:50 PM )	
	Survey held at	48 TOH GUAN ROAD EAST			
	Repairer	M 1 MOTORING			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM22012342/Rwp3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser