

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CS6/AIS22012348/CVP3M4**Date:** 26/07/2023**REFERENCE**

Insured/Claimant: CHAN ZHENG HAO (CHEN ZHENGHAO)
Date of Loss: 03/12/2022

Policy No: SP2002139009-01
Nature of Claim: OD

Claim No: 202222008654

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN2559P**
Make & Model: HONDA CITY, 1.5 SV CVT (A)
Reg. Date: 30/07/2019 (Man. Year: 2019)
Colour: Blue
Engine Capacity: 1497 cc
Market Value/New Car Price: S\$85,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: L15Z16930711
Chassis No: MRHGM6660LT000066
Odometer: 70644 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R16 Rear Tyre Size: 185/55R16
Front Left Side: Hankook 5 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 5 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,095.20	3,799.40	1,295.80	25.43
Miscellaneous Items	70.00	35.00	35.00	50.00
Labour	2,270.00	1,560.00	710.00	31.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,435.20	5,394.40	2,040.80	27.45
- Excess (\$\$)	1,100.00	1,100.00	0.00	0.00
(\$\$)	6,335.20	4,294.40	2,040.80	32.21
+ GST 7.00/8.00% (\$\$)	443.46	343.55	99.91	22.53
Nett Amount (\$\$)	6,778.66	4,637.95	2,140.71	31.58

INSPECTION

Date of Assignment: 08/12/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 12/12/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Estimated Period of Repair: 6.0 days Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: SIMON HO LEONG CHUAN**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2023)
Parts:	143	HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN2559P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc front bumper (WCP)	Distorted	210.00 F	*210.00 F
2	1		*1 pc front bumper reinforcement (WCP)	Bent	245.00 F	*245.00 F
3	1		*2 pcs front bumper side retainers @ \$12/pc (WCP)	Cracked/Cut	24.00 F	*24.00 F
4	1		*1 pc front bumper RH fog lamp cover (WCP)	Cut	18.00 F	*18.00 F
5	1		*1 pc front bumper tow cover (WCP)	Not Necessary	12.00 F	*- F
6	1		*6 pcs front bumper clips @ \$2/pc (WCP)	Necessary	12.00 F	*12.00 F
7	1		*1 pc front bumper lower centre grille (WCP)	Not Necessary	60.00 F	*- F
8	1		*1 pc bonnet (WCP)	Buckled	320.00 F	*320.00 F
9	1		*1 pc bonnet inner lock (WCP)	Cut	80.00 F	*80.00 F
10	1		*2 pcs bonnet hinges @ \$34/pc (WCP)	Bent	68.00 F	*68.00 F
11	1		*2 pcs headlamps @ \$460/pc (WCP)	O/S Cut/ N/S Cracked	920.00 F	*920.00 F
12	1		*2 pcs headlamp lower brackets @ \$34/pc (WCP)	Bent	68.00 F	*68.00 F
13	1		*1 pc RH horn (WCP)	Dented	40.00 F	*40.00 F
14	1		*1 pc front grille housing (WCP)	Cracked	160.00 F	*160.00 F
15	1		*1 pc front grille outer chrome (WCP)	Cracked	98.00 F	*98.00 F
16	1		*1 pc front grille lower chrome (WCP)	Cracked	55.00 F	*55.00 F
17	1		*1 pc front grille stay (WCP)	Bent	15.00 F	*15.00 F
18	1		*1 pc front grille logo (WCP)	Necessary	18.00 F	*18.00 F
19	1		*1 pc front grille inner top garnish (WCP)	Cracked	25.00 F	*25.00 F
20	1		*2 pcs frt fenders @ \$150/pc (WCP)	O/S Buckled	300.00 F	*150.00 F
21	1		*1 pc frt RH fender inner shield (WCP)	Cracked	35.00 F	*35.00 F
22	1		*12 pcs frt fender inner shield clips @ \$3/pc (WCP)	Necessary	36.00 F	*36.00 F
23	1		*1 pc front support panel (WCP)	Repair	290.00 F	*- F
24	1		*1 pc air-con condenser (WCP)	Bent	390.00 F	*390.00 F
25	1		*1 pc air-con outer temp sensor T-bracket (front) (WCP)	Bent	12.00 F	*12.00 F
26	1		*1 pc front RH door (WCP)	Buckled	440.00 F	*440.00 F
27	1		*1 pc front RH door checker (WCP)	Not Necessary	50.00 F	*- F

Report was unsubmitted during this print-out.

7/26/23, 9:52 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*1 pc front RH door lower hinge (WCP)	Not Necessary	36.00 F	*- F
29	1		*1 set front RH door frame sticker (WCP)	Necessary	15.00 F	*15.00 F
30	1		*1 pc front RH door power window motor regulator (WCP)	Not Necessary	220.00 F	*- F
31	1		*1 pc frt RH rim 16 (WCP)	Not Necessary	360.00 F	*- F
F=Franchise part.						
Sub Total (S\$)					4,632.00	3,454.00
+ Margin on L,N Items 10.00/10.00% (S\$)					463.20	345.40
Total Parts (S\$)					5,095.20	3,799.40
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc front number plate Bent	35.00	35.00
2	1	1 unit coolant Not Necessary	35.00	0.00
Sub Total (S\$)			70.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Remove & refix air-con condenser,check,vacuum & refill gas	New	100.00	100.00
2	Remove & refix front bumper & attachments,grille,headlamps,bonnet & attachments,both fenders,frt RH door & attachments;to cut,weld & renew frt support panel;knocking & repair frt chassis frames & realign the same	New	1,000.00	600.00
3	Putty & respray frt bumper,reinforcement,bonnet & attachments,both fenders,frt support panel,frt chassis frames,frt RH door & side mirror,RH rocker panel & all affected areas	New	1,000.00	800.00
4	Remove & refix frt RH door window glass & reset central locking	New	60.00	60.00
5	Remove & refix frt RH rim,tyre,balance & realign the same	New	50.00	0.00
6	To conduct computerised wheel alignment	New	60.00	0.00
Gross Labour Cost (S\$)			2,270.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >