

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012355/TVP3Q2**Date:** 26/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00078882201
Claimant Vehicle No :	SMV4700S	Insured Vehicle No :	GBC2743L
Date of Loss:	19/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208385/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV4700S	Engine No:	CZCA15734
Make & Model:	SEAT TOLEDO, 1.4 (A)	Chassis No:	VSSZZZNHZK1011872
Reg. Date:	30/09/2020 (Man. Year: 2019)	Odometer:	50574 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,774.59	7,286.06	7,488.53	50.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,230.00	1,910.00	3,320.00	63.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,004.59	9,196.06	10,808.53	54.03
Approved Total (Overridden) (S\$)		6,900.00		
(S\$)	20,004.59	6,900.00	13,104.59	65.51
+ GST 8.00/8.00% (S\$)	1,600.37	552.00	1,048.37	65.51
Nett Amount (S\$)	21,604.96	7,452.00	14,152.96	65.51

INSPECTION

Date of Assignment:	18/04/2023	
Date Inspected:	07/12/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jun 2023)	
Parts:	N/A	SEAT TOLEDO 1.4 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV4700S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,811.40 FL	*1,811.40 FL
2	1		*BOOTLID CENRTRE EMBLEM	Necessary	113.00 FL	*113.00 FL
3	1		*BOOTLID TOLEDO EMBLEM	Necessary	133.50 FL	*133.50 FL
4	1		*BOOTLID LH LAMP	Cracked	505.20 FL	*505.20 FL
5	1		*REAR BUMPER	Deformed	1,584.70 FL	*1,584.70 FL
6	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	85.30 FL	*- FL
7	1		*REAR BUMPER LH SIDE RETAINER	Deformed	85.30 FL	*85.30 FL
8	1		*REAR BUMPER LH REVERSE SENSOR	Not Working	303.60 FL	*303.60 FL
9	2		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	15.00 FL	*15.00 FL
10	2		*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	64.00 FL	*64.00 FL
11	1		*LH TAILLAMP ASSY	Necessary	596.70 FL	*596.70 FL
12	1		*LH TAILLAMP PANEL	Repair	194.20 FL	*- FL
13	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	43.00 FL	*- FL
14	1		*END PANEL	Bent	686.70 FL	*686.70 FL
15	1		*END PANEL INNER GARNISH	Not Necessary	231.50 FL	*- FL
16	1		*REAR WINDSCREEN GLASS WITH RUBBER MOULDING	Not Necessary	1,302.80 FL	*- FL
17	1		*REAR LH FENDER	Buckled	1,886.90 FL	*1,886.90 FL
18	1		*REAR LH FENDER SPLASH SHIELD	Not Necessary	95.40 FL	*- FL
19	1		*REAR LH FENDER INNER TRIM BOARD	Not Necessary	552.10 FL	*- FL
20	1		*REAR LH FENDER INNER LOWER AIR DUCT	Not Necessary	93.20 FL	*- FL
21	1		*REAR LH SPORT RIM	Not Necessary	787.90 FL	*- FL
22	1		*REAR LH WHEEL BEARING	Not Necessary	623.70 FL	*- FL
23	1		*REAR LH DOOR	Not Necessary	1,755.30 FL	*- FL
24	1		*REAR LH DOOR WEATHERSTRIP	Not Necessary	231.40 FL	*- FL
25	1		*REAR LH DOOR LOCK	Not Necessary	590.60 FL	*- FL
26	1		*REAR LH DOOR INNER TRIM BOARD	Not Necessary	1,045.30 FL	*- FL
27	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
28	1		*SET REAR BUMPER CLIPS	Not Necessary	80.00 FS	*- FS
29	1		*LH TAILLAMP PANEL JOINT SEAL	Not Necessary	50.00 FS	*- FS
30	1		*END PANEL JOINT SEALANT	Not Working	80.00 FS	*40.00 FS
31	1		*END PANEL INNER GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
32	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
34	1		*REAR LH FENDER JOINT SEALANT	Necessary	100.00 FS	*40.00 FS
35	1		*SET REAR LH FENDER SPLASH SHIELD CLIPS	Not Necessary	70.00 FS	*- FS
36	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Not Necessary	70.00 FS	*- FS
37	1		*REAR BUMPER INNER SPONGE	Deformed	187.40 FL	*187.40 FL
Sub Total (\$\$)						16,335.10 8,083.40
- List Item Discount on L Items 10.00/10.00% (\$\$)						1,560.51 797.34
Total Parts (\$\$)						14,774.59 7,286.06

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE CHECK REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT /WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,600.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,400.00	900.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	SPRAY RUST CHEMICAL COATING ON REPAIRED AND REPLACED PANELS	New	100.00	30.00
5	REMOVE AND REPLACE REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	0.00
6	REMOVE AND REINSTALL ROOF LINING ,SEATS AND CARPET TO ASSIST REPAIR	New	450.00	60.00
7	REMOVE AND REPLACE REAR LH DOOR INNER MECHANISM TO NEW DOOR	New	150.00	0.00
8	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	180.00	0.00
9	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	550.00	0.00
10	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
11	REMOVE AND REPLACE REAR INNER TRIMS ,GARNISH AND BOARDS TO ASSIST REPAIR	New	400.00	60.00
Gross Labour Cost (\$\$)			5,230.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >