



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## OPINION ON REPAIR COST FOR VEHICLE NO. SMM 4487E

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	RADIATOR ASSY	DAMAGED	1,051.00
1	RADIATOR HOSE TOP / BOTTOM	NECESSARY	300.00
1	RADIATOR BYPASS HOSE	NECESSARY	81.40
1	WIPER WASHER TANK	DAMAGED	110.50
1	RADIATOR FAN COWLING	BROKEN	202.00
1	AC CONDENSER	DAMAGED	555.00
1	AC HIGH PRESSURE	NECESSARY	220.00
1	AC LOW PRESSURE	NECESSARY	90.00
1	AC LIQUID PIPE	NECESSARY	504.50
1	AC COMPRESSOR	DAMAGED	2,250.00
1	ALTERNATOR ASSY	DAMAGED	2,499.00
2	RADIATOR STICKERS	NECESSARY	32.36
1	AIR FILTER BOX	DAMAGED	753.40
1	AIR DUCT UP/LH/RH	DAMAGED	130.75
1	AIR DUCT U-HOSE	NECESSARY	35.99
1	FRONT BONNET	DAMAGED	1,400.00
1	FRONT BONNET INSULATOR	NECESSARY	380.00
2	BONNET HINGES @\$145.09	BENT	290.18
1	FRONT BONNET LOCK	DAMAGED	185.00
2	FRONT BONNET RUBBER SEALS @\$65.00	NECESSARY	130.00
4	BONNET STOPPERS @\$23.40	NECESSARY	93.40
1	BONNET DAMPER	DAMAGED	133.00
2	BONNET WIPER NOZZLE @\$85.00	DAMAGED	170.00
2	HALOGEN HEADLAMP @\$836.48	DAMAGED	1,672.96
2	HEADLAMP BRACKET @\$84.90	DAMAGED	169.80
2	HEADLAMP PANEL @\$63.51	DAMAGED	127.02
1	FRONT BUMPER	DAMAGED	1,258.00
2	FRONT BUMPER RETAINERS @\$60.00	NECESSARY	120.00
1	FRONT BUMPER GRILLE ASSY	DAMAGED	833.50
1	FRONT BUMPER LOGO	NECESSARY	45.00
1	FRONT BUMPER TOW COVER	DAMAGED	78.70
2	FOG LAMP COVER @\$95.00	DAMAGED	190.00
1	FRONT BUMPER REINFORCEMENT	BENT	678.70

Report Ref No. CS/LIP22012359/Uqp3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Recommended (\$)
1	FRONT BUMPER REINFORCEMENT SPONGE	NECESSARY	100.00
1	SUPPORT PANEL	BENT	966.00
2	SUPPORT PANEL SIDE GARNISH @\$90.70	NECESSARY	181.40
1	FRONT FENDER LH	DAMAGED	650.00
1	FRONT FENDER INNER SHIELD	NECESSARY / DAMAGED	130.00
1	REAR BUMPER	BENT	971.50
1	REAR BUMPER RETAINER	NECESSARY / BROKEN	88.90
1	REAR R/H REFLECTOR REAR BUMPER	NECESSARY	133.90
1	REAR TAILGATE	DENTED	1,723.90
1	REAR TAILGATE CENTRE LOGO	NECESSARY	87.00
1	"TOURAN" EMBLEM	NECESSARY	80.00
1	"TDI" EMBLEM	NECESSARY	54.00
1	"BLUEMOTION" EMBLEM	NECESSARY	105.15
1	REAR TAILGATE WEATHERSTRIPE	BROKEN	359.10
1	REAR TOW HOOK COVER	BROKEN	40.00
1	REAR TAILGATE LOCK	DAMAGED	133.00
1	FRONT WINDSHIELD	CRACKED	874.00
	LESS 10% DISCOUNT		-2,344.90
			21,104.11
	<b><u>SPECIAL NETT ITEMS</u></b>		
1	SET REAR BUMPER CLIP (SN)	NECESSARY	40.00
1	SET FRONT BONNET CLIPS (SN)	NECESSARY	40.00
1	PLATE NUMBER (F) (SN)	BROKEN	40.00
1	PLATE NUMBER BASE (SN)	BROKEN	20.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	40.00
1	SET FRONT L/H FENDER CLIPS (SN)	NECESSARY	30.00
1	A/C COOLANT (SN)	NECESSARY	50.00
1	WINDSHIELD SEALANT AND MOULDING (SN)	NECESSARY	100.00
			360.00
	<b><u>LABOUR</u></b>		
	PANEL.		1,000.00
	RESPRAY.		800.00
	REMOVE AND REFIX REAR W/SCREEN.		60.00

Report Ref No. CS/LIP22012359/Uqp3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Recommended (\$)
	WIRING.		30.00
	A/C.		30.00
			1,920.00
GRAND TOTAL			23,384.11
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,700.00

Report Ref No. CS/LIP22012359/Uqp3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.