

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22012366/KYA3Q2**Date:** 12/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100181489
Claimant Vehicle No :	SHC5307Y	Insured Vehicle No :	SJV3213Z
Date of Loss:	07/12/2022	Nature of Claim:	TP
		Claim No:	7458620123SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5307Y		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H41571
Reg. Date:	15/01/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FU103093320
Colour:	Metallic Pearl White/Red	Odometer:	235596 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 8 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Wanli 8 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,812.40	3,264.97	2,547.43	43.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,560.00	880.00	7,680.00	89.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	14,372.40	4,144.97	10,227.43	71.16
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	07/12/2022		
Date Inspected:	07/12/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER SUB-ASSY, FRONT LH	Bent	977.80 FL	*977.80 FL
2	1		*LINER, FRONT FENDER, LH	Serviceable	210.30 FL	*- FL
3	1		*EMBLEM, SIDE PANEL	Necessary	54.60 FL	*54.60 FL
4	1		*COVER, FRONT BUMPER	Buckled	521.00 FL	*521.00 FL
5	1		*MOULDING, FRONT BUMPER SIDE, LH	Serviceable	95.60 FL	*- FL
6	1		*REINFORCEMENT SUB-ASSY, FRONT BUMPER	Repair	716.60 FL	*- FL
7	1		*ABSORBER, FRONT BUMPER ENERGY	Serviceable	80.20 FL	*- FL
8	1		*SUPPORT, FRONT BUMPER SIDE, LH	Distorted	82.30 FL	*82.30 FL
9	1		*STAY SUB-ASSY, FRONT BUMPER, LH	Serviceable	47.50 FL	*- FL
10	1		*BRACKET, FRONT BUMPER SIDE, LH	Repair	59.30 FL	*- FL
11	1		*UNIT ASSY, HEADLAMP, LH	Mtg Cracked	2,637.60 FL	*2,637.60 FL
12	1		*GRILLE SUB-ASSY, RADIATOR	Serviceable	422.50 FL	*- FL
13	1		*GRILLE, RADIATOR, LOWER NO.1	Serviceable	178.60 FL	*- FL
14	1		*MIRROR ASSY, OUTER REAR VIEW, LH	Serviceable	1,339.30 FL	*- FL
15	1		*SET BUMPER CLIP FRT	Necessary	95.00 FS	*60.00 FS
16	1		*SET FRNT BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
17	1		*FRT FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
					Sub Total (\$\$)	7,668.20 4,333.30
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,855.80 1,068.33
					Total Parts (\$\$)	5,812.40 3,264.97

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,000.00	400.00
3	TO REMOVE AND REFIT ELECTRICAL WIRING, BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
4	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
9	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (S\$)			8,560.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >