

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22012381/AWY3E2**Date:** 23/03/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002057341
Claimant Vehicle No :	SKK5893T	Insured Vehicle No :	SCH8182C
Date of Loss:	08/12/2022	Nature of Claim:	TP
		Claim No:	293806

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK5893T	Engine No:	CTH003151
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI 1623Q5 (A)	Chassis No:	WVWZZZ16ZDM023091
Reg. Date:	01/08/2013 (Man. Year: 2012)	Odometer:	162905 km
Colour:	Grey		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,067.60	11,265.90	5,801.70	33.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,850.00	2,300.00	2,550.00	52.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,917.60	13,565.90	8,351.70	38.10
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	21,917.60	8,000.00	13,917.60	63.50

INSPECTION

Date of Assignment:	12/12/2022	Hua Meng Spray Painting Workshop (HQ)
Date Inspected:	12/12/2022 Inspected At:	No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit
Estimated Period of Repair:	8.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2023)
Parts:	143	VOLKSWAGEN JETTA 1.4 TSI 1623Q5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK5893T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,147.00 FL	*1,147.00 FL
2	1		*FRONT BUMPER RH SIDE HOLDER	Not Necessary	75.00 FL	*- FL
3	1		*FRONT RH LAMP	Not Necessary	1,955.00 FL	*- FL
4	1		*FRONT RH FENDER	Distorted	571.00 FL	*571.00 FL
5	1		*FRONT RH FENDER INNER SHIELD	Deformed	198.00 FL	*198.00 FL
6	1		*FRONT RH FENDER INNER REAR GARNISH	Not Necessary	125.00 FL	*- FL
7	1		*FRONT RH DOOR SIDE MIRROR }	Not Necessary	536.00 FL	*- FL
8	1		*FRONT RH DOOR SIDE MIRROR HOUSING }		0.00 FL	*- FL
9	1		*FRONT RH DOOR SIDE MIRROR COVER }		0.00 FL	*- FL
10	1		*FRONT RH DOOR	Distorted	1,381.00 FL	*1,381.00 FL
11	1		*FRONT RH DOOR GLASS TOP MOULDING	Not Necessary	185.00 FL	*- FL
12	1		*FRONT RH DOOR OUTER HANDLE	Not Necessary	204.00 FL	*- FL
13	1		*FRONT RH DOOR LOCK	Damaged	375.00 FL	*375.00 FL
14	1		*FRONT RH DOOR KEY LOCK COVER	Not Necessary	80.00 FL	*- FL
15	1		*FRONT RH DOOR TOP HINGE	Bent	132.00 FL	*132.00 FL
16	1		*FRONT RH DOOR LOWER HINGE	Bent	132.00 FL	*132.00 FL
17	1		*FRONT RH DOOR STOPPER	Not Necessary	58.00 FL	*- FL
18	1		*FRONT RH DOOR BOARD	Cracked	736.00 FL	*736.00 FL
19	1		*FRONT RH DOOR POWER WINDOW REGULATOR	Damaged	298.00 FL	*298.00 FL
20	1		*FRONT RH DOOR POWER WINDOW MOTOR	Not Necessary	372.00 FL	*- FL
21	1		*FRONT RH DOOR GLASS INNER FRAME	Not Necessary	149.00 FL	*- FL
22	1		*FRONT RH DOOR GLASS FRAME MOULDING	Not Necessary	130.00 FL	*- FL
23	1		*FRONT RH DOOR SPEAKER	Cracked	205.00 FL	*205.00 FL
24	1		*FRONT RH DOOR INNER LOWER RUBBER	Necessary	168.00 FL	*168.00 FL
25	1		*FRONT RH SHOCK ABSORBER	Bent	488.00 FL	*488.00 FL
26	1		*FRONT RH LOWER ARM	Bent	445.00 FL	*445.00 FL
27	1		*FRONT RH DRIVE SHAFT	Not Necessary	1,680.00 FL	*- FL
28	1		*FRONT RH LINKAGE	Not Necessary	149.00 FL	*- FL
29	1		*STEERING RACK	Bent	4,230.00 FL	*4,230.00 FL
30	1		*FRONT RH DISC PLATE	Not Necessary	115.00 FL	*- FL
31	1		*REAR RH DOOR	Dented	1,298.00 FL	*1,298.00 FL
32	1		*REAR RH DOOR SIDE RUBBER	Necessary	147.00 FL	*147.00 FL
33	1		*FRONT RH SPORT RIM	Cut	800.00 FS	*480.00 FS
34	1		*FRONT RH TYRE	Not Necessary	250.00 FS	*- FS
35	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,844.00	12,461.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,776.40	1,195.10
Total Parts (\$)	17,067.60	11,265.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
2	TOWING FEE	New	150.00	60.00
3	REMOVE & REFIX FRONT WINDSCREEN	New	200.00	0.00
4	REMOVE & REFIX DESKBOARD	New	400.00	0.00
5	REMOVE & REFIX FRONT SUSPENSION	New	500.00	300.00
6	REMOVE & REFIX DOOR FITTINGS	New	200.00	160.00
7	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	900.00
8	RESPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			4,850.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >