

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP MSIG.
Xin/6

ESTIMATE

Vehicle No : SKK 5893 T

Chassis No: WVWZZZ16ZDM023091

Make/Model : VOLKSWAGEN JETTA

Accident date : 08.12.2022

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Front bumper <i>Detached</i>	1	\$ 1147
2	Front bumper RH side holder <i>Not nec</i>	1	\$ 75
3	Front RH lamp <i>Not nec</i>	1	\$ 1955
4	Front RH fender <i>Distorted</i>	1	\$ 571
5	Front RH fender inner shield <i>Detached</i>	1	\$ 198
6	Front RH fender inner rear garnish <i>Not nec</i>	1	\$ 125
7	Front RH door side mirror <i>Not Nec</i>	1	\$ 536
8	Front RH door side mirror housing	1	\$
9	Front RH door side mirror cover	1	\$
10	Front RH door <i>Distorted</i>	1	\$ 1381
11	Front RH door glass top moulding <i>Not nec</i>	1	\$ 185
12	Front RH door outer handle <i>Not nec</i>	1	\$ 204
13	Front RH door lock <i>Damaged</i>	1	\$ 375
14	Front RH door key lock cover <i>Not nec</i>	1	\$ 80
15	Front RH door top hinge <i>Bent</i>	1	\$ 132
16	Front RH door lower hinge	1	\$ 132
17	Front RH door stopper <i>Not nec</i>	1	\$ 58
18	Front RH door board <i>Cracked</i>	1	\$ 736
19	Front RH door power window regulator <i>Damaged</i>	1	\$ 298
20	Front RH door power window motor <i>Not nec</i>	1	\$ 372
21	Front RH door glass inner frame <i>Not nec</i>	1	\$ 149
22	Front RH door glass frame moulding <i>Not nec</i>	1	\$ 130
23	Front RH door speaker <i>Cracked</i>	1	\$ 205
24	Front RH door inner lower rubber <i>Not nec</i>	1	\$ 168
25	Front RH shock absorber <i>Bent</i>	1	\$ 488
26	Front RH lower arm <i>Bent</i>	1	\$ 445
27	Front RH drive shaft <i>Not nec</i>	1	\$ 1680
28	Front RH linkage <i>Not nec</i>	1	\$ 149
29	Steering rack <i>Bent</i>	1	\$ 4230
30	Front RH discs plate <i>Not nec</i>	1	\$ 115
31	Rear RH door <i>Dented</i>	1	\$ 1298
32	Rear RH door side rubber <i>Not nec</i>	1	\$ 147

11851

Less 10% Disc

Total

10755.90

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SKK 5893 T

Chassis No: WVWZZZ16ZDM023091

Make/Model : VOLKSWAGEN JETTA

Accident date : 08.12.2022

No	DESCRIPTION	Qty	Amount (\$\$)
Special Nett Items			
1	Front RH sport rim <i>ut</i>	1	\$ <i>800</i> 480.
2	Front RH tyre <i>not new</i>	1	\$ <i>250</i> X.
3	Front RH fender inner shield clips (1 set) <i>new</i>	1	\$ <i>30</i> ✓
		Total	\$ <i>510</i>
Labour Cost			
1	To check wheel alignment		\$ 100.00 80
2	Towing fee		\$ 150.00 60.
3	Remove & refix front windscreen		\$ 200.00 X
4	Remove & refix deskboard		\$ 400.00 X
5	Remove & refix front suspension		\$ 500.00 300.
6	Remove & refix door <i>glass fittings</i>		\$ 200.00 160
7	Remove ,replace & repair consistent to the accident		\$ 1,800.00 900
8	Respray painting		\$ 1,500.00 800.
		Total	\$ 4,850.00
		Grand Total	\$ <i>2300</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 13565.90

h/s: 8K
(Nett Value).

10 Days.

8K