1/16/23, 10:49 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Policy No:

Nature of Claim:

Allianz Insurance Singapore Pte. Ltd.

Our File No:

CS6/AIS22012382/DVY3E2

79 Robinson Road #09-01 Singapore 068897

Date:

16/01/2023

REFERENCE

Date of Loss:

Insured/Claimant: RAJESHKUMAR MADAWLAL SHARMA

SP2000729631

OD

031

202222008729

DESCRIPTION & IDENTIFICATION OF VEHICLE

07/12/2022

Reg No:

SJV1129Y

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FC9U775761

Reg. Date:

12/01/2010 (Man. Year: 2009)

Chassis No:

Odometer:

KMHDU41BMAU933391

Claim No:

Colour:

Silver

1591 cc

Engine Capacity: Market Value/New Car

2445 222

Price:

S\$15,000.00

Sum Insured (S\$):

Market Value/New Car Price

185/65 R15

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes

Footbrake (Serviceable):

161598 km

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

.00

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Rear Tyre Size: Rear Left Side: 185/65 R15 Falken 5 mm

Front Right Side:

Falken 5 mm Falken 5 mm

Rear Right Side:

Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		599.50	599.50	0.00	0.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,000.00	770.00	230.00	23.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	1,599.50	1,369.50	230.00	14.38
	Approved Total (Overridden) (S\$)		1,100.00		
	(S\$)	1,599.50	1,100.00	499.50	31.23
	+ GST 7.00/7.00% (S\$)	111.97	77.00	34.97	31.23
	Nett Amount (S\$)	1,711.47	1,177.00	534.47	31.23

INSPECTION

Date of Assignment: 12/12/2022 Present Location:

2.0 days

Falcon-Air Auto Services Pte Ltd (Tampines)
Falcon-Air Auto Services Pte Ltd (Tampines)

Date Inspected:

13/12/2022 Inspected At:

Blk 9006 #01-200 Tampines St 93

Singapore 528840

Estimated Period of Repair:

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jan 2023)

Parts: 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJV1129Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S WING MIRROR (WCP)	Damaged	285.00 F	*285.00 F
2	1		*N/S WING MIRROR GLASS (WCP)	Cracked	85.00 F	*85.00 F
3	1		*N/S WING MIRROR GLASS COVER (WCP)	Cut	60.00 F	*60.00 F
4	1		*N/S WING MIRROR LAMP (WCP)	Cracked	85.00 F	*85.00 F
5	1		*N/S WING MIRROR EMBLEMN (WCP)	Necessary	30.00 F	*30.00 F
F=Fra	anchise	part.				
				Sub Total (S\$)	545.00	545.00
			+ Margin o	on L,N Items 10.00/10.00% (S\$)	54.50	54.50
				Total Parts (S\$)	599.50	599.50

Report was unsubmitted during this print-out.

1/16/23, 10:49 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
<u>Lab</u>	Labour Items								
1	TO CHECK WIRING	New	50.00	20.00					
2	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	350.00	300.00					
3	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	600.00	450.00					
	Gross Labour Cost (S\$)		1,000.00	770.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >