

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22012384/UNY3E2**Date:** 30/12/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001506634

**Claimant Vehicle No :** SML6902R**Insured Vehicle No :** SMF2849U

Date of Loss: 08/12/2022

Nature of Claim: TP Claim No: 294241

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SML6902R**

Make &amp; Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB7101931

Reg. Date: 30/05/2019 (Man. Year: 2018)

Chassis No: GP72001400

Colour: Blue

Odometer: 122910 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Roadstone 6 mm

Rear Left Side: Roadstone 6 mm

Front Right Side: Roadstone 6 mm

Rear Right Side: Roadstone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,911.36	3,294.56	1,616.80	32.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,210.00	850.00	41.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,971.36</b>	<b>4,504.56</b>	<b>2,466.80</b>	<b>35.38</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,971.36</b>	<b>3,600.00</b>	<b>3,371.36</b>	<b>48.36</b>

INSPECTION

Date of Assignment: 13/12/2022

Date Inspected: 12/12/2022 Inspected At:

Quan De Motor Trading  
 BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY  
 SINGAPORE 417883  
 Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 27 Dec 2022)	
<b>Parts:</b>	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML6902R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	981.00 FL	*963.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Bent	45.50 FL	*45.50 FL
3	1		*HEADLAMP (LED) RH	Scratched / Cracked	2,680.00 FL	*2,235.00 FL
4	1		*FRONT FENDER RH	Dented	545.20 FL	*545.20 FL
5	1		*FRONT FENDER INNER SHIELD RH	Twisted	182.00 FL	*182.00 FL
6	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	85.00 FL	*85.00 FL
7	1		*FRONT LOWER ARM RH	Not Necessary	322.60 FL	*- FL
8	1		*FRONT KNUCKLE ARM RH	Not Necessary	385.40 FL	*- FL
9	1		*FRONT KNUCKLE ARM BEARING RH	Not Necessary	225.00 FL	*- FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
11	1		*FRONT SPORT RIM RH	Repair	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,001.70</b>	<b>4,105.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,090.34	811.14
<b>Total Parts (\$\$)</b>	<b>4,911.36</b>	<b>3,294.56</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	60.00	20.00
2	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
3	TO REMOVE & REFIX UNDERCARRIAGE	New	180.00	0.00
4	TO SPRAY RUST PROOFING	New	100.00	30.00
5	LABOUR FOR PANEL BEATING ,WELDING AND RENEW PARTS	New	800.00	400.00
6	SPRAY PAINTING	New	800.00	700.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,060.00</b>	<b>1,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >