

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22012385/UWY3M4**Date:** 01/02/2023**REFERENCE**

Insured/Claimant: SATHANANTHAM NAGARAJAN Policy No: DMPG22012433
Date of Loss: 08/12/2022 Nature of Claim: OD Claim No: CDMPG22002650

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ7744A**
Make & Model: TOYOTA HARRIER, 2.0 G GRADE (A) Engine No: 8ARZ154993
Reg. Date: 26/04/2019 (Man. Year: 2019) Chassis No: JTEKB3GH80J004366
Colour: White Odometer: 56137 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$118,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Yokohama 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,255.60	21,239.90	8,015.70	27.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,265.64	6,093.64	2,172.00	26.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,521.24	27,333.54	10,187.70	27.15
- Excess (S\$)	3,700.00	3,700.00	0.00	0.00
(S\$)	33,821.24	23,633.54	10,187.70	30.12
+ GST 7.00/7.00% (S\$)	2,367.49	1,654.35	713.14	30.12
Nett Amount (S\$)	36,188.73	25,287.89	10,900.84	30.12

INSPECTION

Date of Assignment: 12/12/2022
Date Inspected: 12/12/2022 Inspected At: Borneo Motors (S) Pte Ltd (Ubi)
17 Ubi Road 4
Singapore 408611
Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2023)
Parts: M1-SUV	TOYOTA HARRIER 2.0 G GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMZ7744A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, FR BUMPER	Distorted	811.30 FS	*811.30 FS
2	1		*RETAINER, FR BUMPER (N/S)	Not Necessary	115.20 FS	*- FS
3	1		*RETAINER, FR BUMPER (O/S)	Bent	115.20 FS	*115.20 FS
4	2		*CLIP, PIN HOLD	Necessary	4.20 FS	*4.20 FS
5	2		*RETAINER, FR FENDER	Bent	34.00 FS	*34.00 FS
6	1		*ABSORBER, FR BUMPER	Torn	54.40 FS	*54.40 FS
7	1		*RETAINER, FR BUMPER	Bent	117.40 FS	*117.40 FS
8	1		*REINFORCEMENT	Not Necessary	301.10 FS	*- FS
9	1		*ABSORBER, FR BUMPER,	Torn	185.00 FS	*185.00 FS
10	1		*MOULDING SUB-ASSY,	Cut	465.60 FS	*465.60 FS
11	1		*GUARD, FR BUMPER	Distorted	340.20 FS	*340.20 FS
12	1		*DAMPER, SUSPENSION	Not Necessary	1,533.00 FS	*- FS
13	10		*PIECE, RR BUMPER	Necessary	49.00 FS	*49.00 FS
14	1		*GRILLE SUB-ASSY,	Cut	497.30 FS	*497.30 FS
15	1		*CLIP	Necessary	3.00 FS	*3.00 FS
16	1		*PANEL, FR FENDER, RH	Buckled	1,446.30 FS	*1,446.30 FS
17	1		*LINER, FR FENDER, RH	Torn	522.50 FS	*522.50 FS
18	10		*CLIP	Necessary	43.00 FS	*43.00 FS
19	1		*PROTECTOR, FR FENDER	Not Necessary	109.30 FS	*- FS
20	1		*HINGE ASSY, HOOD, RH	Not Necessary	87.10 FS	*- FS
21	1		*PANEL SUB-ASSY, FR DOOR	Repair	2,035.90 FS	*- FS
22	1		*UNIT, HEADLAMP	Cracked	7,996.60 FS	*7,996.60 FS
23	1		*REINFORCEMENT, FR	Not Necessary	69.80 FS	*- FS
24	1		*BRACKET, HEADLAMP, A	Not Necessary	36.10 FS	*- FS
25	1		*COMPUTER SUB-ASSY,	Not Necessary	1,342.50 FS	*- FS
26	1		*COMPUTER SUB-ASSY,	Not Necessary	1,294.80 FS	*- FS
27	1		*LAMP ASSY, FOG	Not Necessary	516.00 FS	*- FS
28	1		*LAMP ASSY, DAYTIME	Scratched/Cracked	966.30 FS	*966.30 FS
29	2		*RETAINER, ULTRASONIC	Necessary	37.00 FS	*37.00 FS
30	1		*SENSOR, ULTRASONIC, (2Pieces)	Shorted (1Piece Only)	963.80 FS	*481.90 FS
31	2		*RETAINER, ULTRASONIC	Necessary	48.40 FS	*48.40 FS
32	1		*CLIP, ULTRASONIC	Necessary	14.30 FS	*14.30 FS
33	1		*JAR, WASHER, A	Deformed	173.20 FS	*173.20 FS
34	1		*CAP, WASHER, A	Not Necessary	93.00 FS	*- FS
35	1		*WHEEL, DISC	Cut	2,970.70 FS	*2,970.70 FS
36	1		*ABSORBER ASSY,	Bent	683.80 FS	*683.80 FS
37	1		*LINK ASSY, FR	Bent	196.20 FS	*196.20 FS
38	1		*ARM SUB-ASSY,	Bent	969.10 FS	*969.10 FS
39	1		*JOINT ASSY, LWR BALL	Bent	314.60 FS	*314.60 FS
40	1		*KNUCKLE, STEERING,	Bent	875.10 FS	*875.10 FS
41	1		*HUB&BEARING ASSY,	Damaged	794.30 FS	*794.30 FS
42	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	29,255.60	21,239.90
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE & ININSTALL FRT SENSOR	New	198.00	198.00
2	CHECK LIGHTING & WIRING SYSTEM	New	134.64	134.64
3	TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR	New	198.00	198.00
4	TO RESET ECU AND REPROGRAMME	New	198.00	198.00
5	REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING	New	99.00	99.00
6	REPLACE RH FRT SUSPENSION SYSTEM	New	792.00	792.00
7	CONDUCT FULL WHEEL ALIGNMENT	New	198.00	198.00
8	REPLACE FRT RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT RH ACCIDENT AFFECTED AREAS	New	3,168.00	1,980.00
9	RESPRAY JOB ON FRT RH ACCIDENT AFFECTED AREAS	New	3,280.00	2,296.00
			Gross Labour Cost (S\$)	8,265.64
				6,093.64

Report was unsubmitted during this print-out.

< END OF ESTIMATES >