

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22012387/RVP3E2**Date:** 02/03/2023**REFERENCE**

Insured/Claimant:	AW SUAT HUAY (HU XUEHUI)	Policy No:	2070109311
Date of Loss:	06/12/2022	Nature of Claim:	OD Claim No: 8110051765SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP838Z		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM024112
Reg. Date:	29/07/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF50LA018353
Colour:	Blue	Odometer:	14513 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$177,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,419.00	10,454.32	4,964.68	32.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,032.00	3,852.00	3,180.00	45.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,451.00	14,306.32	8,144.68	36.28
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	21,651.00	13,506.32	8,144.68	37.62
+ GST 8.00/8.00% (\$\$)	1,732.08	1,080.51	651.57	37.62
Nett Amount (\$\$)	23,383.08	14,586.83	8,796.25	37.62

INSPECTION

Date of Assignment:	12/12/2022	
Date Inspected:	09/12/2022	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE - RH	Cracked	72.00 FS	*57.20 FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	151.00 FS	*- FS
6	1		*FRONT BUMPER OUTER GRILLE HOLE COVER - RH	Not Necessary	54.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Cracked	41.00 FS	*32.24 FS
8	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
9	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
10	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
11	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	266.00 FS	*- FS
12	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
13	1		*FRONT FENDER - RH	Bent	1,189.00 FS	*951.20 FS
14	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
15	1		*FRONT FENDER CLOSING ELEMENT - RH	Necessary	83.00 FS	*65.84 FS
16	1		*FRONT FENDER BRACKET - RH FRONT	Necessary	41.00 FS	*32.72 FS
17	6		*FRONT FENDER RIVET	Necessary	23.00 FS	*18.24 FS
18	1		*FRONT FENDER BRACE - RH	Bent	132.00 FS	*105.20 FS
19	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	55.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - RH CENTER	Not Necessary	40.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER - RH	Torn	299.00 FS	*238.80 FS
22	1		*FRONT WHEEL SPOILER	Cracked	82.00 FS	*65.12 FS
23	1		*FRONT WHEEL SPOILER END PLATE - RH	Not Necessary	40.00 FS	*- FS
24	1		*FRONT WHEEL SPOILER STONE CHIP GUARD - RH	Not Necessary	57.00 FS	*- FS
25	1		*FRONT WHEEL SPOILER TRIM BRACKET - RH	Not Necessary	27.00 FS	*- FS
26	1		*FRONT FENDER CHROME TRIM - RH	Necessary	171.00 FS	*136.40 FS
27	1		*FRONT DOOR CHROME TRIM - RH	Necessary	171.00 FS	*136.40 FS
28	1		*FRONT FENDER LEDGE COVER - LONG	Cracked	40.00 FS	*31.44 FS
29	1		*FRONT FENDER LEDGE COVER - RH SHORT	Not Necessary	18.00 FS	*- FS
30	1		*HEADLIGHT COVER - RH	Cracked	49.00 FS	*38.64 FS
31	1		*HEADLIGHT - RH	Cracked	8,172.00 FS	*6,537.60 FS
32	1		*LIFT CYLINDER - RH	Not Necessary	217.00 FS	*- FS
33	1		*LIFT CYLINDER BRACKET - RH	Cracked	17.00 FS	*12.88 FS
34	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
35	1		*LIFT CYLINDER CORRUGATED HOSE	Not Necessary	53.00 FS	*- FS
36	1		*LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
37	1		*RHS FRONT RIM	Not Necessary	0.00 FS	*- FS
			(NPA)			
38	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 15,419.00 10,454.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR	New	3,000.00	1,650.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,032.00	3,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >