



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE		Ref: CC4/ASM22012390/Apa3q2 Date: 04/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 5713T	Veh. Inspected	SJV 9806Z
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04FRH	Excess (\$)	0.00
Assign From		Assign Date	12/12/2022
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO FORTE KOUP	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFW611MA5203332	Colour	BLACK
Odometer	182180 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/11/2022	Inspection Date	12/12/2022
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	