

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

OLIVEIRO DION MARK
 BLK 488B TAMPINES ST 45 #03-149
 SINGAPORE 521488

Contact : 97683761

TAX INVOICE

Repair Code : CLM17518
 Date in : 12/12/2022
 Vehicle Num. : SJV9806Z
 Model : KIA CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
 Chassis/Eng# : KNAFW611MA5203332/G4FCAH365696

TP AXA
 Xiao Long

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER REINFORCEMENT <i>Replaced</i>	1	278.00	✓ 278.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	32.00	+ 64.00
FRONT FENDER L/R <i>new Rep</i>	2	569.00	+ 1,138.00
FRONT LH HEADLAMP <i>cut</i>	1	540.00	✓ 540.00
FRONT LH HEADLAMP LOWER BRACKET <i>Best</i>	1	68.00	✓ 68.00
FRONT SUPPORT PANEL <i>cut</i>	1	435.00	✓ 435.00
Subtotal before discount			2,523.00
Percentage discount 10%			252.30
Sub-total 1			2,270.70
FRONT BUMPER <i>Distorted</i>	1	1600.00	<i>800</i> 1,600.00
FRONT BUMPER LH FOGLAMP <i>cut</i>	1	480.00	<i>280</i> 480.00
FRONT BUMPER LH SIDE GUIDE <i>new</i>	1	60.00	+ 60.00
Subtotal before discount			2,140.00
Percentage discount 0%			0.00
Sub-total 2			2,140.00
Parts-total			4,410.70

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

30 ~~80.00~~
400 ~~1,000.00~~

Kari Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

OLIVEIRO DION MARK
BLK 488B TAMPINES ST 45 #03-149
SINGAPORE 521488

Contact : 97683761

TAX INVOICE

Repair Code : CLM17518
Date in : 12/12/2022
Vehicle Num. : SJV9806Z
Model : KIA CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
Chassis/Eng# : KNAFW611MA5203332/G4FCAH365696

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,180.00
Parts & Labour Total	6,590.70

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

whl: 3328.50

L/S: 2.6k ✓

L/S 05 days

Adrian Lj
12/12/22

500 1,000.00
30 100.00