

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012394/TVP3Q2**Date:** 07/06/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00246692201

**Claimant Vehicle
No :** SGD8688J**Insured Vehicle
No :** SLS800R

Date of Loss: 08/12/2022

Nature of Claim: TP

Claim
No: SNM22D208856/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SGD8688J**

Make & Model: VOLKSWAGEN SHARAN, 1.8 (A)

Engine No: DED012455

Reg. Date: 30/06/2017 (Man. Year: 2017)

Chassis No: WVVZZZ7NZHV236734

Colour: Grey

Odometer: 93910 km

Engine Capacity: 1984 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,728.41	5,053.32	8,675.09	63.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	530.00	2,700.00	83.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,958.41	5,583.32	11,375.09	67.08
Approved Total (Overridden) (S\$)		4,450.00		
(S\$)	16,958.41	4,450.00	12,508.41	73.76
+ GST 8.00/8.00% (S\$)	1,356.67	356.00	1,000.67	73.76
Nett Amount (S\$)	18,315.08	4,806.00	13,509.08	73.76

INSPECTION

Date of Assignment: 12/12/2022

Date Inspected: 13/12/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts:	M1-MPV	VOLKSWAGEN SHARAN 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGD8688J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,214.59 FL	*1,620.00 FL
2	1		*FRONT BUMPER LH SIDE CORNER PARKING SENSOR	Not Working	190.18 FL	*190.18 FL
3	1		*FRONT BUMPER LH SIDE PARKING SENSOR	Not Necessary	190.18 FL	*- FL
4	1		*FRONT BUMPER LH CENTRE PARKING SENSOR	Not Necessary	190.18 FL	*- FL
5	6		*FRONT BUMPER PARKING SENSOR RUBBER SEAL	Not Necessary	22.35 FL	*- FL
6	1		*FRONT BUMPER LH FOG LAMP	Cracked	372.13 FL	*302.00 FL
7	1		*FRONT BUMPER LH FOG LAMP COVER	Cut	189.91 FL	*189.91 FL
8	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	221.54 FL	*- FL
9	1		*FRONT BUMPER CENTRE GRILLE CHROME MOULDING	Not Necessary	220.19 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	734.58 FL	*- FL
11	1		*FRONT BUMPER CENTRE BRACKET	Not Necessary	155.32 FL	*- FL
12	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	31.35 FL	*- FL
13	1		*FRONT BUMPER LH SIDE RETAINER	Cracked	31.35 FL	*31.35 FL
14	1		*FRONT BUMPER RH INNER BRACKET	Not Necessary	33.19 FL	*- FL
15	1		*FRONT BUMPER LH INNER BRACKET	Not Necessary	33.19 FL	*- FL
16	1		*LH HEADLAMP	Cut	2,669.12 FL	*2,242.00 FL
17	1		*LH HEADLAMP NOZZLE COVER	Cut	26.00 FL	*26.00 FL
18	1		*LH HEADLAMP NOZZLE	Cracked	235.66 FL	*235.66 FL
19	1		*LH HEADLAMP UPPER PANEL	Not Necessary	53.39 FL	*- FL
20	1		*RH HEADLAMP	Not Necessary	2,736.03 FL	*- FL
21	1		*FRONT GRILLE	Cracked	606.73 FL	*606.73 FL
22	1		*FRONT GRILLE EMBLEM	Necessary	115.42 FL	*115.42 FL
23	1		*SUPPORT PANEL	Not Necessary	905.02 FL	*- FL
24	1		*AIRCON CONDENSER	Not Necessary	876.95 FL	*- FL
25	1		*RADIATOR ASSY	Not Necessary	783.37 FL	*- FL
26	1		*FRONT LH FENDER	Not Necessary	872.62 FL	*- FL
27	1		*FRONT LH FENDER SPLASH SHIELD	Not Necessary	221.03 FL	*- FL
28	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
29	1		*SET FRONT GRILLE CLIPS	Necessary	60.00 FS	*20.00 FS
30	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
31	1		*SET FRONT LH FENDER SPLASH SHIELD CLIPS	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,221.57	5,609.25
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,493.16	555.93
Total Parts (\$\$)	13,728.41	5,053.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,300.00	250.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	250.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	70.00	0.00
5	REFOCUS AND ADJUSYT HEADLAMPS ASSY	New	80.00	0.00
6	REMOVE AND REPLACE AIRCON CONDENSER ,PIPES AND HOSES TO ASSIST REPAIR .TO REFILL GAS	New	220.00	0.00
7	REMOVE AND REPLACE RADIATOR ASSY ,HOSES AND FAN ASSY TO ASSIST REPAIR .TO REFILL COOLANT	New	280.00	0.00
Gross Labour Cost (S\$)			3,230.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >