

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Repair Estimate**

Vehicle number: SGD8688J

Make &amp; Model: Volkswagen Sharan

Chassis number: WVWZZZ7NZHV236734

Date of survey:

Name of surveyor:

Contacts:

| No. | Description of spare parts                 | Qty | Amount S\$                  |
|-----|--------------------------------------------|-----|-----------------------------|
| 1   | Front bumper                               | 1   | \$ <del>de</del> 2,214.59   |
| 2   | Front bumper LH side corner parking sensor | 1   | \$ <del>sw</del> 190.18     |
| 3   | Front bumper LH side parking sensor        | 1   | \$ x <del>g</del> 190.18    |
| 4   | Front bumper LH centre parking sensor      | 1   | \$ x <del>gun</del> 190.18  |
| 5   | Front bumper parking sensor rubber seal    | 6   | \$ x <del>g</del> 22.35     |
| 6   | Front bumper LH fog lamp                   | 1   | \$ <del>cm</del> 372.13     |
| 7   | Front bumper LH fog lamp cover             | 1   | \$ <del>art</del> 189.91    |
| 8   | Front bumper centre grille                 | 1   | \$ x 221.54                 |
| 9   | Front bumper centre grille chrome moulding | 1   | \$ x <del>g</del> 220.19    |
| 10  | Front bumper reinforcement                 | 1   | \$ x <del>gun</del> 734.58  |
| 11  | Front bumper centre bracket                | 1   | \$ x 155.32                 |
| 12  | Front bumper RH side retainer              | 1   | \$ x <del>g</del> 31.35     |
| 13  | Front bumper LH side retainer              | 1   | \$ <del>cm</del> 31.35      |
| 14  | Front bumper RH inner bracket              | 1   | \$ x <del>un</del> 33.19    |
| 15  | Front bumper LH inner bracket              | 1   | \$ x <del>un</del> 33.19    |
| 16  | LH headlamp                                | 1   | \$ <del>art</del> 2,669.12  |
| 17  | LH headlamp nozzle cover                   | 1   | \$ <del>art</del> 26.00     |
| 18  | LH headlamp nozzle                         | 1   | \$ <del>cm</del> 235.66     |
| 19  | LH headlamp upper panel                    | 1   | \$ x <del>un</del> 53.39    |
| 20  | RH headlamp                                | 1   | \$ x <del>un</del> 2,736.03 |
| 21  | Front grille                               | 1   | \$ <del>cm</del> 606.73     |
| 22  | Front grille emblem                        | 1   | \$ <del>un</del> 115.42     |
| 23  | Support panel                              | 1   | \$ x <del>g</del> 905.02    |
| 24  | Aircon condenser                           | 1   | \$ x <del>g</del> 876.95    |
| 25  | Radiator assy                              | 1   | \$ x <del>g</del> 783.37    |
| 26  | Front LH fender                            | 1   | \$ x 872.62                 |
| 27  | Front LH fender splash shield              | 1   | \$ x <del>g</del> 221.03    |

\$ 14,931.57  
 Parts less 10% \$ 1,493.16  
 Total \$ 13,438.41

| No. | Special Nett Items                  | Qty  | Amount S\$                 |
|-----|-------------------------------------|------|----------------------------|
| 1   | Front bumper clips                  | 1set | \$ <del>30 All</del> 80.00 |
| 2   | Front grille clips                  | 1set | \$ <del>20 All</del> 60.00 |
| 3   | Radiator coolant                    | 1    | \$ x <del>un</del> 80.00   |
| 4   | Front LH fender splash shield clips | 1set | \$ x <del>un</del> 70.00   |

Total: \$ 290.00

| No. | Labour and painting                                                                                                                            | Amount S\$  |
|-----|------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| 1   | Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas | \$ 1,300.00 |
| 2   | Spray painting on affected areas and panels                                                                                                    | \$ 1,200.00 |
| 3   | Check wiring and lighting system on affected areas                                                                                             | \$ 80.00    |
| 4   | Apply rust coating chemical on affected areas and panels                                                                                       | \$ 70.00    |
| 5   | Refocus and adjusyt headlamps assy                                                                                                             | \$ 80.00    |
| 6   | Remove and replace aircon condenser, pipes and hoses to assist repair. To refill gas                                                           | \$ 220.00   |
| 7   | Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant                                                       | \$ 280.00   |
|     | Total:                                                                                                                                         | \$ 3,230.00 |

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)  
Working days: \_\_\_\_\_

7601.12

L/S - 6080.89  
= 6100

|               |    |           |
|---------------|----|-----------|
| Spare Parts:  | \$ | 13,438.41 |
| Special Nett: | \$ | 290.00    |
| Labour:       | \$ | 3,230.00  |

**Total Amount: \$ 16,958.41**

Tanpik 9749549  
WP 13/12/22 @ 5pm  
L/S Resing after repair  
tanpik @ lkhauto.com  
- To check consistency of accident  
- To check part prices  
o 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: \_\_\_\_\_  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_