

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012397/TNP3Q2**Date:** 25/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00200852202
Claimant Vehicle No :	SFG2361L	Insured Vehicle No :	SKG4482Z
Date of Loss:	09/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D208892/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFG2361L	Engine No:	K24W71011244
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRC1890FC202541
Reg. Date:	20/08/2015 (Man. Year: 2015)	Odometer:	245015 km
Colour:	Silver		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,260.63	4,972.26	2,288.37	31.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,955.00	9,795.00	6,160.00	38.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,215.63	14,767.26	8,448.37	36.39
+ GST 8.00/8.00% (S\$)	1,857.25	1,181.38	675.87	36.39
Nett Amount (S\$)	25,072.88	15,948.64	9,124.24	36.39

INSPECTION

Date of Assignment:	12/12/2022		
Date Inspected:	15/12/2022	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2023)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFG2361L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*MOULDING WINDSHIELD SIDE	Necessary	28.80 FS	*28.80 FS
2	1		*MOULDINGL RR.WINDSHIELD CORNER	Necessary	13.57 FS	*13.57 FS
3	1		*MOULDINGR RR.WINDSHIELD CORNER	Necessary	13.57 FS	*13.57 FS
4	4		*SPACERRR.W/SHIELD	Necessary	12.60 FS	*12.60 FS
5	1		*RUBBER A WINDSHIELD DAM	Necessary	2.92 FS	*2.92 FS
6	1		*DAMPERSTD 5X5 (2 PCS)	Necessary	13.65 FS	*13.65 FS
7	1		*CAPPIVOT	Necessary	3.90 FS	*3.90 FS
8	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
9	1		*EMBLEMH	Necessary	21.15 FS	*21.15 FS
10	1		*LIGHT ASSY ,R.LID	Cracked	310.05 FS	*310.05 FS
11	1		*LIGHT ASSYL.LID	Cracked	310.05 FS	*310.05 FS
12	1		*TAILLIGHT ASSYR	Not Necessary	672.90 FS	*- FS
13	1		*TAILLIGHT ASSYL	Not Necessary	672.90 FS	*- FS
14	1		*BUZZER ASSYSMART	Not Necessary	48.22 FS	*- FS
15	1		*ANTENNA ASSY,L.RR	Cracked	48.60 FS	*48.60 FS
16	1		*LINING ASSYTAILGATE LOWER	Deformed	165.60 FS	*165.60 FS
17	1		*POCKETTAILGATE LINING PULL	Not Necessary	8.62 FS	*- FS
18	1		*LINING ASSYRR PANEL	Deformed	83.17 FS	*83.17 FS
19	1		*FACERR,BUMPER	Deformed	456.22 FS	*456.22 FS
20	1		*SPACERR.RR.BUMPER SIDE	Not Necessary	15.30 FS	*- FS
21	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	15.30 FS	*- FS
22	1		*CLIP BUMPER (7 PCS)	Necessary	12.07 FS	*12.07 FS
23	1		*PANEL COMP REAR	Bent	369.90 FS	*369.90 FS
24	1		*PAN SET 3RD SEAT	Repair	271.27 FS	*- FS
25	1		*TAILGATE COMP	Bent	859.65 FS	*859.65 FS
26	1		*WEATHERSTRIP TAILGATE	Cut	94.27 FS	*94.27 FS
27	1		*MOLDING ASSYRR.LICENSE GARN	Not Necessary	140.92 FS	*- FS
28	1		*LOCKTAILGATE	Not Necessary	150.30 FS	*- FS
29	1		*GARNISH ASSYRR.LICENSE	Not Necessary	185.02 FS	*- FS
30	4		*ACT RR SENSOR	Not Working	320.00 FS	*320.00 FS
31	1		*OILSHEET	Not Necessary	32.62 FS	*- FS
32	1		*NUMBER PLATE WITH CASING -L	Not Necessary	45.00 FS	*- FS
33	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
34	1		*AUTO TAIL GATE -ODY	Jammed	960.75 FS	*960.75 FS
35	1		*LINING COMP,R.RR.SIDE	Deformed	589.20 FS	*589.20 FS
36	1		*MOLDING ASSYRR.LICENSE GARN	Cracked	140.92 FS	*140.92 FS
37	1		*FACEL .RR BUPER GARNISH	Deformed	61.65 FS	*61.65 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)7,260.634,972.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	150.00
2	REMOVE & INSTALL REVERSE SENSORS	New	200.00	150.00
3	BODY JOINT SEALANT	New	200.00	100.00
4	BODY UNDERSIDE COATING	New	200.00	100.00
5	APPLY BODY UNDERSIDE COATING	New	450.00	250.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	650.00	350.00
7	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
8	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	350.00
9	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	0.00
10	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	650.00	0.00
11	REMOVE & INSTALL RR SEATS TRUNK LININGS GARNISHES	New	650.00	0.00
12	REMOVE & INSTALL RR WINDSCREEN	New	650.00	650.00
13	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	650.00	650.00
14	CUT & RENEW RR FLOOR PANEL STRAIGHTEN FENDERS ALIG	New	5,500.00	3,250.00
15	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	4,300.00	3,120.00
16	RENEW AUTO TAILGATE AND RESET SETTING	New	325.00	325.00
Gross Labour Cost (S\$)			15,955.00	9,795.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >