



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SLQ 3540G

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRT BUMPER	NECESSARY / BUCKLED	745.00
1	FRT BUMPER CLIPS	NECESSARY / DISLODGE	35.00
1	FRT BUMPER SIDE RETAINER LH	CRACKED	85.00
1	FRT LH BUMPER FOG LAMP COVER	CUT	49.00
1	FRT LH BUMPER FOG LAMP	* CHECK	-
1	FRT LH HEADLAMP ASSY	* CHECK	-
1	FRT LH FENDER	TO REPAIR SEE LABOUR	-
1	FRT LH FENDER PROTECTOR	DISLODGE	195.00
1	FRT LH FENDER INNER SHIELD	* CHECK	-
	LESS 20% DISCOUNT		-221.80
			887.20
	<u>LABOUR</u>		
	REPLACING ACCIDENT DAMAGED PARTS, KNOCK/JACK & STRAIGHTEN ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRT LH FENDER.		500.00
	SPRAY PAINTING ACCIDENT AFFECTED AREAS.		600.00
	CHECKING ELECTRICAL WIRING & LIGHTING SYSTEM FOR PROPER FUNCTION.		30.00
			1,130.00
	GRAND TOTAL		2,017.20

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (EXCLUDE CHECK ITEMS S\$1,716.00 NETT)	1,600.00
--	-----------------

Report Ref No. CS3/SPF22012407/Gvy3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,600-\$2,200

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.