

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22012411/UVY3Q2**Date:** 23/12/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SKV3219X**Insured Vehicle No :** XE3641U

Date of Loss: 09/12/2022

Nature of Claim: TP

Claim No: 2022 22009033/FR

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKV3219X**

Make & Model: ADIVA AD1 200, 190cc 3W

Engine No: L15B4028656

Reg. Date: 02/03/2016 (Man. Year: 2015)

Chassis No: RU11108654

Colour: Blue

Odometer: 164302 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Dayton 6 mm

Rear Left Side:

Dayton 6 mm

Front Right Side: Dayton 6 mm

Rear Right Side:

Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,583.01	3,404.00	4,179.01	55.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,240.00	1,760.00	58.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,583.01	4,644.00	5,939.01	56.12
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	10,583.01	3,700.00	6,883.01	65.04

INSPECTION

Date of Assignment: 12/12/2022

Date Inspected: 19/12/2022 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)
25 Kaki Bukit Road 4, #01-49 Synergy@KB
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Dec 2022)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV3219X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Cut	1,085.40 FL	*825.10 FL
2	1		*FRONT BUMPER LOWER LID	Grazed	489.10 FL	*420.00 FL
3	1		*FRONT BUMPER FOG LAMP	Not Necessary	327.70 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	45.26 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINERS	N/S Cracked	120.60 FL	*60.50 FL
6	1		*FRONT HEADLAMPS	Holder Cracked	1,784.50 FL	*1,128.10 FL
7	1		*FRONT FENDER -L	Dented	580.40 FL	*580.40 FL
8	1		*FRONT FENDER INNER SHIELDS -L	Torn	155.20 FL	*155.20 FL
9	1		*FRONT FENDER WHEEL ARCH GARNISH -L	Grazed	388.30 FL	*240.20 FL
10	1		*FRONT WHEEL RIMS	Repair	1,350.40 FL	*- FL
11	1		*FRONT LOWER ARMS	Not Necessary	426.00 FL	*- FL
12	1		*FRONT SHOCK ABSORBER	Not Necessary	502.70 FL	*- FL
13	1		*FRONT WHEEL BEARINGS	Not Necessary	363.00 FL	*- FL
14	1		*FRONT KNUCKLE ARMS	Not Necessary	589.70 FL	*- FL
15	1		*FRONT DOOR SIDE MIRROR ASSY -L	Grazed	745.50 FL	*745.50 FL
16	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*40.00 FS
17	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*40.00 FS
18	1		*FRONT TYRES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,373.76	4,235.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,790.75	831.00
Total Parts (\$)	7,583.01	3,404.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT FRONT UNDERCARRIAGE	New	500.00	0.00
2	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
3	TO APPLY UNDERCOATING	New	120.00	30.00
4	PANEL BEATING	New	1,000.00	400.00
5	TO RESPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	750.00
Gross Labour Cost (\$\$)			3,000.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >